WO#: 2019 00855

91SA

1710

Cirrus

SR-20

5959.2

Reg#:

MFG:

Model:

A/C Tach Time:

AC S/N:

RMS
Resource Maintenance System

Work Order

Western Michigan University College of Aviation

FAA CertificatedRepair Station JX8R258Q 237 N Helmer Road, Battle Creek, MI 49037 Date Started: 06/11/19
Date Completed: 06/17/19

A/C Total Time: 5959.2
RT Eng. T.T.:
RT Prop. T.T.
LT Eng T.T.: 1975.2
LT Prop T.T.: 4122.2

	Description of Work to be Performed
1)	ETA squawk: Flaps won't come back up

1) ETA	squawk: Flaps won't come	back up					
		Maintenance/Repairs Pe	rformed				
1) ETA s	squawk: Flaps won't come	back up					
	alled new flap relays. (ps check good.					
		Labor					
Kevin Sol	lt 0.5 000:30					0:30	
		Parts Used					
Qty	Part#	Description	Serial#	Cost	t L	Sub Total	
2 50288-001 Relay, Flap or Circuit Panel (Alt P/N V23234-A0004-X051)					9.56	19.12	
Technician Release					Work Order Totals		
Buy Back Test FLT Tech Signature: Tech#:						37.50	
		· · · · · · · · · · · · · · · · · · ·		Parts		19.12	
Maintenance Release						56.62	
The aircraft, airframe, aircraft engine, propeller or appliance identified above, was inspected and repaired in accordance with current Regulations of the Federal Aviation Administration and is approved for return to service. Pertinent details of the repair/inspection are on file at the Repair Station under this Work Order.					Preliminary / Hidden Inspection Release		
	re: S FAA CertificatedRepair Station J	Signed: X8R258Q . 237 N Helmer Road, Battle Cree	ek, MI 49037	Date: _ Inspector: _			