WO#: 2021 01514

Reg#:

MFG:

Model:

AC S/N:

Western Michigan University **College of Aviation**

Work Order

A/C Total Time: 7240.1 RT Eng. T.T.: RT Prop. T.T. LT Eng T.T.: 1034.8 LT Prop T.T.: 5610.5

09/25/21

09/29/21

Date Started:

Date Completed:

A/C Tach Time: 7240.1

91SA

1710

Cirrus

SR-20

FAA CertificatedRepair Station JX8R258Q 237 N Helmer Road, Battle Creek, MI 49037

Description of Work to be Performed				
1) ETA squawk: after landing,	flaps inop			
Maintenance/Repairs Performed				
1) ETA squawk: after landing, Airframe:	flaps inop			
removed and replaced both f	lap relays			
Labor				
Travis Meyer 0.5 000:30				
				0:30
	Parts Used			
Qty Part#	Description	Serial#	Cost	Sub Total
2 50288-001 Relay, Flap or Circuit Panel (Alt P/N V23234-A0004-X051)			13.36	26.72
Technician Release			Work Order Totals	
Buy Back ☐ Test FLT ☐ Tech Signature: Tech#:			Labor	37.50
			Parts	26.72
Maintenance Release			TOTAL:	64.22
The aircraft, airframe, aircraft engine, propeller or appliance identified above, was inspected and repaired in accordance with current Regulations of the Federal Aviation Administration and is approved for return to service. Pertinent details of the repair/inspection are on file at the Repair Station under this Work Order.			Preliminary / Hidden Inspection Release Date:	
Date: Signed: WMU FAA CertificatedRepair Station JX8R258Q . 237 N Helmer Road, Battle Creek, MI 49037			Inspector:	