WO#: 2017 00201

91SA

1710

Cirrus

SR-20

4809.7

Reg#:

MFG:

Model:

A/C Tach Time:

AC S/N:

RMS
Resource Maintenance System

Resource Maintenance System Work Order

Western Michigan University College of Aviation

FAA CertificatedRepair Station JX8R258Q 237 N Helmer Road, Battle Creek, MI 49037 Date Started: 02/20/17
Date Completed: 02/22/17

A/C Total Time: 4809.7 RT Eng. T.T.: RT Prop. T.T.

LT Eng T.T.: 819.2 LT Prop T.T.: 2966.2

	Description of Work to	be Performed		
1) RH white position light	in-op			
	Maintenance/Repairs	Performed		
1) RH white position light i Airframe:	n-op			
RH position light bulb re	placed. Ops check good.			
	Labor			
Ajitpal Singh 1.0 000:60				
				1:00
	Parts Used			
Qty Part#	Description	Serial#	Cost	Sub Total
1 34-0428070-64	White Position Light (A508-28)		22.	80 22.80
Technician Release			Work Order Totals	
Buy Back Test FLT Tech Signature:		Tech#:	Labor	75.00
			Parts	22.80
Maintenance Release			TOTAL:	97.80
The aircraft, airframe, aircraft engine, propeller or appliance identified above, was inspected and repaired in accordance with current Regulations of the Federal Aviation Administration and is approved for return to service. Pertinent details of the repair/inspection are on file at the Repair Station under this Work Order.		Preliminary / Hidden Inspection Release		
Date:	_ Signed:tion JX8R258Q . 237 N Helmer Road. Battle		Date: Inspector:	