WO#: 2014 00526

91SA

1710

Cirrus

SR-20

3698.3

Reg#:

MFG:

Model:

A/C Tach Time:

AC S/N:

Work Order

Western Michigan University **College of Aviation**

FAA CertificatedRepair Station JX8R258Q 237 N Helmer Road, Battle Creek, MI 49037

Date Started: 05/06/14 Date Completed: 05/08/14

A/C Total Time:	3698.3
RT Eng. T.T.:	
RT Prop. T.T.	
LT Eng T.T.:	1712.9
LT Prop T.T.:	3709.9

Description of Work to be Performed								
1) RH	strobe and white posit	-						
1) RH strobe and white position light inop.								
Maintenance/Repairs Performed								
1) RH strobe and white position light inop. Airframe: Replaced RH strobe power supply and flash tube. Replaced RH white position light bulb.								
Labor								
John Fra	anklin 2.0 002:00					2:00		
Parts Used								
Qty	Part#	Description	Serial# Cos		Cost	Sub Total		
1	34-0428070-64	White Position Light (A508-28)	-		20.92	20.92		
1	50625-001	Strobe Power Supply (Alt P/N			427.60	427.60		
1	50909-001	01-0770062-05) Strobe Light (Alt P/N 36-0050705-00)			72.80	72.80		
Technician Release			Work Order Totals					
Buy Back ☐ Test FLT ☐ Tech Signature: Tech#:		1	lbor irts	120.00 521.32				
Maintenance Release			TC	TAL:	641.32			
The aircraft, airframe, aircraft engine, propeller or appliance identified above, was inspected and repaired in accordance with current Regulations of the Federal Aviation Administration and is approved for return to service. Pertinent details of the repair/inspection are on file at the Repair Station under this Work Order. Date: Signed:		Preliminary / Hidden Inspection Release Date:						
WMU FAA CertificatedRepair Station JX8R258Q . 237 N Helmer Road, Battle Creek, MI 49037			Ins	pector:				