WO#: 2015 01878

91SA

1710

Cirrus

SR-20

4328.7

Reg#:

MFG:

Model:

A/C Tach Time:

AC S/N:

Western Michigan University College of Aviation

Work Order

10/23/15 Date Started: Date Completed: 10/27/15

A/C Total Time:	4328.
RT Eng. T.T.:	
RT Prop. T.T.	

LT Eng T.T.: 341.8 LT Prop T.T.: 2488.8

FAA CertificatedRepair Station JX8R258Q 237 N Helmer Road, Battle Creek, MI 49037

Description of Work to be Performed					
1) L position light inop					
	Maintenance/Repairs Pe	rformed			
1) L position light inop Airframe:	•				
Replaced bulb. ops check g	ood.				
	Labor				
Jonathan 0.5 000:30 Dennis				0:30	
	Parts Used				
Qty Part#	Description	Serial#	Cost	Sub Total	
1 34-0428070-64	White Position Light (A508-28)		20.46	20.46	
Technician Release			Work Order Totals		
Buy Back Test FLT Tech Signature: Tech#:		- · · ·	Labor Parts	37.50 20.46	
Maintenance Release			TOTAL:	57.96	
The aircraft, airframe, aircraft engine, propeller or appliance identified above, was inspected and repaired in accordance with current Regulations of the Federal Aviation Administration and is approved for return to service. Pertinent details of the repair/inspection are on file at the Repair Station under this Work Order.		Preliminary / Hidden Inspection Release			
Date:	Signed: n JX8R258Q . 237 N Helmer Road, Battle Cree	.	Date: nspector:		