WO#: 2019 01314

91SA

1710

Cirrus

SR-20

6121.4

Reg#:

MFG:

Model:

A/C Tach Time:

AC S/N:

RMS
Resource Maintenance System

Work Order

Voctors Michigan Lini

Western Michigan University College of Aviation

FAA CertificatedRepair Station JX8R258Q 237 N Helmer Road, Battle Creek, MI 49037 Date Started: 08/09/19
Date Completed: 08/09/19

A/C Total Time:	6121.		
RT Eng. T.T.:			
RT Prop. T.T.			

LT Eng T.T.: 2124.4 LT Prop T.T.: 4271.4

Description of Work to be Performed							
1) Flap	os wont retract						
		Maintenance/Repairs Pe	rformed				
Airframe:	wont retract alled new up and down fla	up relays.					
		Labor					
Nathan St	cewart 0.5 000:30				0:30		
		Parts Used					
Qty	Part#	Description	Serial#	Cost	Sub Total		
2 !	50288-001	Relay, Flap or Circuit Panel (Alt P/N V23234-A0004-X051)		9.40	18.80		
Technician Release				Work Order Totals			
Buy Back Test FLT Tech Signature: Tech#:		Labor	37.50				
				Parts	18.80		
Maintenance Release			TOTAL:	56.30			
The aircraft, airframe, aircraft engine, propeller or appliance identified above, was inspected and repaired in accordance with current Regulations of the Federal Aviation Administration and is approved for return to service. Pertinent details of the repair/inspection are on file at the Repair Station under this Work Order.		Preliminary / Hidden Inspection Release Date:					
Date	e:	Signed:					
WMU FAA CertificatedRepair Station JX8R258Q . 237 N Helmer Road, Battle Creek, MI 49037				Inspector:			