WO#: 2019 01465

91SA

1710

Cirrus

SR-20

6156.0

Reg#:

MFG:

Model:

A/C Tach Time:

AC S/N:

Western Michigan University College of Aviation

Work Order

Date Started: Date Completed:

09/03/19

08/31/19

A/C Total Time: 6156.0

RT Eng. T.T.: RT Prop. T.T.

LT Eng T.T.: 2161.3 LT Prop T.T.: 4308.3

FAA CertificatedRepair Station JX8R258Q 237 N Helmer Road, Battle Creek, MI 49037 Description of Work to be Performed

1) ETA squawk: Flaps won't retract	
Maintenance/Repairs Performed	
1) ETA squawk: Flaps won't retract Airframe:	
r/r flap relay ops check good	
Labor	
James Bacik 1.0 001:00	
	1:00
Parts Used	
Qty Part# Description Serial# Cost Sub '	Total
2 50288-001 Relay, Flap or Circuit Panel (Alt 9.62 P/N V23234-A0004-X051)	19.24
Technician Release Work Order Tot	als
Buy Back Test FLT Tech Signature: Tech#: Labor	75.00
Parts	19.24
Maintenance Release TOTAL:	94.24
The aircraft, airframe, aircraft engine, propeller or appliance identified above, was inspected and repaired in accordance with current Regulations of the Federal Aviation Administration and is approved for return to service. Pertinent details of the repair/inspection are on file at the Repair Station under this Work Order.	
Date:	
Date: Signed: WMU FAA CertificatedRepair Station JX8R258Q . 237 N Helmer Road, Battle Creek, MI 49037 Inspector:	