WO#: 2021 00066

91SA

1710

Cirrus

SR-20

6768.4

Reg#:

MFG:

Model:

A/C Tach Time:

AC S/N:

Work Order

Western Michigan University College of Aviation

FAA CertificatedRepair Station JX8R258Q 237 N Helmer Road, Battle Creek, MI 49037

Date Started: 01/23/21 Date Completed: 01/27/21

A/C Total Time: 6768.4 RT Eng. T.T.:

LT Eng T.T.: 554.7 LT Prop T.T.: 5130.4

RT Prop. T.T.

Description of Work to be Performed

1) ETA	squawk: flaps won't go	up				
		Maintenance/Repairs Pe	rformed			
_	squawk: flaps won't go u	p				
Airframe:		_				
Insta	alled new flap up and do	wn relays.				
		Labor				
Rusty Wir	nston 1.0 001:00					
						1:00
		Parts Used				
Qty	Part#	Description	Serial#		Cost	Sub Total
2	50288-001	Relay, Flap or Circuit Panel (Alt P/N V23234-A0004-X051)			13.87	27.74
Technician Release				Work Order Totals		
Buy Back Test FLT Tech Signature: Tech#: Tech#:				La	abor	75.00
		<u> </u>		Pa	arts	27.74
Maintenance Release				TO	TAL:	102.74
The aircraft, airframe, aircraft engine, propeller or appliance identified above, was inspected and repaired in accordance with current Regulations of the Federal Aviation Administration and is approved for return to service. Pertinent details of the repair/inspection are on file at the Repair Station under this Work Order.				Preliminary / Hidden Inspection Release		
		Signed: JX8R258Q 237 N Helmer Road, Battle Crev	ek MI 49037	Da Ins	te: spector:	