WO#: 2020 01050

RIMS
Resource Maintenance System
Work Order

 Reg#:
 91SA

 AC S/N:
 1710

 MFG:
 Cirrus

 Model:
 SR-20

 A/C Tach Time:
 6560.3

Western Michigan University College of Aviation

FAA CertificatedRepair Station JX8R258Q 237 N Helmer Road, Battle Creek, MI 49037

Date Started: 09/22/20

Date Completed: 09/22/20

A/C Total Time: 6560.3

RT Eng. T.T.: RT Prop. T.T.

LT Eng T.T.: 342.8

LT Prop T.T.: 4918.5

Description of Work to be Performed				
1) LH white position light out.				
	Maintenance/Repairs Pe	erformed		
1) LH white position light out. Airframe:				
Replaced LH white position li	ight bulb. Ops check good.			
	Labor			
Pam Jones 0.5 000:30				
				0:30
	Parts Used			
Qty Part#	Description	Serial#	Cost	Sub Total
1 34-0428070-64	White Position Light (A508-28)		40.40	40.40
Technician Release			Work Order Totals	
Buy Back Test FLT Tech Signature: Tech#:		Tech#:	Labor	30.00
			Parts	40.40
Maintenance Release			TOTAL:	70.40
The aircraft, airframe, aircraft engine, propeller or appliance identified above, was inspected and repaired in accordance with current Regulations of the Federal Aviation Administration and is approved for return to service. Pertinent details of the repair/inspection are on file at the Repair Station under this Work Order.		stration and is	Preliminary / Hidden Inspection Release	
			Date:	
Date: Signed: WMU FAA CertificatedRepair Station JX8R258Q . 237 N Helmer Road, Battle Creek, MI 49037			Inspector:	