WO#: 2016 01420

91SA

1710

Cirrus

SR-20

4750.5

Reg#:

MFG:

Model:

A/C Tach Time:

AC S/N:

Work Order

## **Western Michigan University College of Aviation**

FAA CertificatedRepair Station JX8R258Q 237 N Helmer Road, Battle Creek, MI 49037

Date Started: 11/22/16 Date Completed: 11/29/16

A/C Total Time: 4750.5 RT Eng. T.T.:

RT Prop. T.T. LT Eng T.T.: 762.8

2909.8

LT Prop T.T.:

Description of Work to be Performed							
1)	Left Position light out						

1) Left Po	osition light out								
Maintenance/Repairs Performed									
1) Left Pos	sition light out								
	and replaced LH posit	ion bulb. Ops check good.							
		Labor							
Justine Fos	ter 0.5 000:30					0:30			
		Parts Used							
Qty	Part#	Description	Serial#		Cost	Sub Total			
1 34-	-0428070-64	White Position Light (A508-28)			22.80	22.80			
	Г	Work Order Totals							
Buy Back	☐ Test FLT☐Tecl	Labor Parts		37.50 22.80					
	M	TOTAL:		60.30					
The aircraft, airframe, aircraft engine, propeller or appliance identified above, was inspected and repaired in accordance with current Regulations of the Federal Aviation Administration and is approved for return to service. Pertinent details of the repair/inspection are on file at the Repair Station under this Work Order.					Preliminary / Hidden Inspection Release				
		Signed: X8R258Q . 237 N Helmer Road, Battle Cre	ek, MI 49037	Date:	ctor:				