WO#: 2019 00890

91SA

1710

Cirrus

SR-20

5970.9

Reg#:

MFG:

Model:

A/C Tach Time:

AC S/N:

Work Order

## **Western Michigan University College of Aviation**

FAA CertificatedRepair Station JX8R258Q 237 N Helmer Road, Battle Creek, MI 49037 Date Started: 06/14/19 Date Completed: 06/17/19

A/C Total Time:	5970.
RT Eng. T.T.:	
RT Prop. T.T.	
LT Eng T.T.:	1975.
LT Prop T.T.:	4122.

	Description of Work to be Performed							
1)	Flaps would not lower							

1) Flag	ps would not lower					
		Maintenance/Repairs Pe	erformed			
1) Flaps	s would not lower					
Airframe	:					
Inst	alled up and down flap	relays.				
		Labor				
Nathan S	tewart 0.5 000:30					
						0:30
		Parts Used				
Qty	Part#	Description	Serial#		Cost	Sub Total
2	50288-001	Relay, Flap or Circuit Panel (Alt P/N V23234-A0004-X051)			9.49	18.98
Technician Release				Work Order Totals		
Buy Ba	.ck 🔲 Test FLT 🔲 Te	ch Signature:	Tech#:	Lá	abor	37.50
				Pá	arts	18.98
		Maintenance Release		T	:JATC	56.48
The aircraft, airframe, aircraft engine, propeller or appliance identified above, was inspected and repaired in accordance with current Regulations of the Federal Aviation Administration and is approved for return to service. Pertinent details of the repair/inspection are on file at the Repair Station under this Work Order.			Preliminary / Hidden Inspection Release			
Dat	te:	Signed: n JX8R258Q . 237 N Helmer Road, Battle Cre	ek. MI 49037	-	ite: spector:	