WO#: 2019 01760

91SA

1710

Cirrus

SR-20

6213.7

Reg#:

MFG:

Model:

A/C Tach Time:

AC S/N:

Work Order

Western Michigan University College of Aviation

FAA CertificatedRepair Station JX8R258Q 237 N Helmer Road, Battle Creek, MI 49037

10/14/19 Date Started: Date Completed: 10/16/19

A/C Total Time: 6213.7 RT Eng. T.T.:

RT Prop. T.T. LT Eng T.T.: 2220.5 LT Prop T.T.: 4367.5

	Description of Work to be Performed								
1)	LH white position light inop								

I) LH WIIILE POS	sition light inop						
		Maintenance/Repairs Pe	rformed				
1) LH white posi Airframe:	tion light inop						
Installed new	w left hand white	e position light. Ops check good.					
		Labor					
Kevin Luther	0.5 000:30						
						0:30	
		Parts Used					
Qty	Part#	Description	Serial#		Cost	Sub Total	
1 34-04280	70-64	White Position Light (A508-28)			37.04	37.04	
	Work Order Totals						
Buy Back Test FLT Tech Signature: Tech#:				Labor		37.50	
	Parts		37.04				
	TOTAL:		74.54				
The aircraft, airframe, aircraft engine, propeller or appliance identified above, was inspected and repaired in accordance with current Regulations of the Federal Aviation Administration and is approved for return to service. Pertinent details of the repair/inspection are on file at the Repair Station under this Work Order. Date: Signed: WMU FAA CertificatedRepair Station JX8R258Q . 237 N Helmer Road, Battle Creek, MI 49037					Preliminary / Hidden Inspection Release		
					Date:		