WO#: 2015 00829

91SA

1710

Cirrus

SR-20

4138.6

Reg#:

MFG:

Model:

A/C Tach Time:

AC S/N:

Work Order

Western Michigan University College of Aviation

FAA CertificatedRepair Station JX8R258Q 237 N Helmer Road, Battle Creek, MI 49037

06/01/15 Date Started: Date Completed: 06/02/15

A/C Total Time: 4138.6 RT Eng. T.T.: RT Prop. T.T.

LT Eng T.T.: 147.8 LT Prop T.T.: 2294.8

| Description of Work to be Performed | | | | |
|---|--------------------------------|---|-------------------|----------------|
| 1) RH white aft nav light out | | | | |
| | | | | |
| | Maintenance/Repairs Pe | rformed | | |
| 1) RH white aft nav light out Airframe: | | | | |
| Replaced RH white position I | ight. | | | |
| | Labor | | | |
| Curran McGuire 0.5 000:30 Jus | tine Foster 0.5 000:30 | | | |
| | | | | 1:00 |
| | Parts Used | | | |
| Qty Part# | Description | Serial# | Cost | Sub Total |
| 1 34-0428070-64 | White Position Light (A508-28) | | 22.8 | 30 22.80 |
| Technician Release | | | Work Order Totals | |
| Buy Back ☐ Test FLT ☐ Tech Signature: Tech#: | | | Labor Parts | 75.00 22.80 |
| Maintenance Release | | | TOTAL: | 97.80 |
| The aircraft, airframe, aircraft engine, propeller or appliance identified above, was inspected and repaired in accordance with current Regulations of the Federal Aviation Administration and is approved for return to service. Pertinent details of the repair/inspection are on file at the Repair Station under this Work Order. | | Preliminary / Hidden Inspection Release | | |
| Date: Signed: Date: Inspector: | | | | |