WO#: 2021 01091

91SA

1710

Cirrus

SR-20

7102.4

Reg#:

MFG:

Model:

A/C Tach Time:

AC S/N:

Work Order **Western Michigan University College of Aviation**

Date Started: 07/20/21 Date Completed: 07/26/21

A/C Total Time: 7102.4

RT Eng. T.T.: RT Prop. T.T.

LT Eng T.T.: 890.8 LT Prop T.T.: 5466.5

FAA CertificatedRepair Station JX8R258Q 237 N Helmer Road, Battle Creek, MI 49037

Description of Work to be Performed				
1) R position light inop				
Maintenance/Repairs Performed				
1) R position light inop Airframe:				
Installed new right position	light bulb. Ops check good.			
Labor				
Jonathan 1.0 001:00 Dennis				
Demiis				1:00
	Parts Used			
Qty Part#	Description	Serial#	Cost	Sub Total
1 34-0428070-64	White Position Light (A508-28)		41.99	41.99
Technician Release			Work Order Totals	
Buy Back Test FLT Tech Signature: Tech#:		Labor	75.00	
			Parts	41.99
Maintenance Release			TOTAL:	116.99
The aircraft, airframe, aircraft engine, propeller or appliance identified above, was inspected and repaired in accordance with current Regulations of the Federal Aviation Administration and is approved for return to service. Pertinent details of the repair/inspection are on file at the Repair Station under this Work Order.		Preliminary / Hidden Inspection Release		
			Date:	
Date: Signed: WMU FAA CertificatedRepair Station JX8R258Q . 237 N Helmer Road, Battle Creek, MI 49037			Inspector:	