WO#: 2021 00441

91SA

1710

Cirrus

SR-20

6898.6

Reg#:

MFG:

Model:

A/C Tach Time:

AC S/N:

Work Order

Western Michigan University College of Aviation

FAA CertificatedRepair Station JX8R258Q 237 N Helmer Road, Battle Creek, MI 49037

Date Started: 03/25/21 Date Completed: 03/25/21

6898.6 A/C Total Time: RT Eng. T.T.:

RT Prop. T.T.

LT Eng T.T.: 681.1 LT Prop T.T.: 5256.8

	Description of Work to be Performed						
1)	flaps wouldn't come down to 100% when selected, then would come down ater						

		2 050111011 01 11 01 11 00 00 1	6110111100				
1) flaps wo	uldn't come down to	o 100% when selected, then would come	e down ater				
		Maintenance/Repairs Per	rformed				
1) flaps wou Airframe:	ldn't come down to	100% when selected, then would come	down ater				
Installed	l new flap motor a	nd relays. adjusted rigging ref AMM					
		Labor					
Jeff Nilsson	3.0 003:00					3:00	
		Parts Used					
Qty	Part# Description		Serial#		Cost	Sub Total	
	8-001	Relay, Flap or Circuit Panel (Alt P/N V23234-A0004-X051)			13.86	27.72	
1 1178	7-003	Flap Actuator (Alt P/N 11787-403)		_	2,882.25	2,882.25	
		Work Order Totals					
Buy Back Test FLT Tech Signature: Tech#:					abor arts	180.00 2,909.97	
Maintenance Release					TAL:	3,089.97	
The aircraft, airframe, aircraft engine, propeller or appliance identified above, was inspected and repaired in accordance with current Regulations of the Federal Aviation Administration and is approved for return to service. Pertinent details of the repair/inspection are on file at the Repair Station under this Work Order.					Preliminary / Hidden Inspection Release		
Date:		Signed:	k, MI 49037	Da	te: :pector:		