WO#: 2019 00794

91SA

1710

Cirrus

SR-20

5935.4

Reg#:

MFG:

Model:

A/C Tach Time:

AC S/N:

Work Order

Western Michigan University College of Aviation

06/05/19 Date Started: Date Completed: 06/05/19

A/C Total Time: 5935.4 RT Eng. T.T.:

LT Eng T.T.: 1938.4 LT Prop T.T.: 4085.4

RT Prop. T.T.

FAA CertificatedRepair Station JX8R258Q 237 N Helmer Road, Battle Creek, MI 49037

Description of Work to be Performed				
1) LH white position light out				
	Maintenance/Repairs Pe	erformed		
LH white position light out Airframe: replaced bulb				
Jeff Nilsson 0.3 000:15	Labor			
Jeff Nilsson 0.3 000:15		Total L	abor Hours:	0.3 0:15
	Parts Used			
Qty Part#	Description	Serial#	Cost	Sub Total
1 34-0428070-64	White Position Light (A508-28)		32.16	32.16
Technician Release			Work Order Totals	
Buy Back ☐ Test FLT ☐ Tech Signature: Tech#:		Tech#:	Labor Parts	15.00 32.16
Maintenance Release			TOTAL:	47.16
The aircraft, airframe, aircraft engine, propeller or appliance identified above, was inspected and repaired in accordance with current Regulations of the Federal Aviation Administration and is approved for return to service. Pertinent details of the repair/inspection are on file at the Repair Station under this Work Order.			Preliminary / Hidden Inspection Release Date:	
Date: Signed: WMU FAA CertificatedRepair Station JX8R258Q . 237 N Helmer Road, Battle Creek, MI 49037			Inspector:	