WO#: 2018 00475

Reg#:

MFG:

Model:

A/C Tach Time:

AC S/N:

Work Order

Western Michigan University College of Aviation

04/02/18 Date Started: Date Completed: 04/09/18

A/C Total Time:	5345.
RT Eng. T.T.:	
RT Prop. T.T.	

LT Eng T.T.: 1365.6 LT Prop T.T.: 3512.6

FAA CertificatedRepair Station JX8R258Q 237 N Helmer Road, Battle Creek, MI 49037

91SA

1710

Cirrus

SR-20

5345.6

Description of Work to be Performed				
1) right white pos light ou	t			
	Maintenance/Denaire	Doufoumod		
	Maintenance/Repairs	reriorineu		
<pre>1) right white pos light out Airframe:</pre>				
replaced right white nav				
Labor				
Kevin Solt 0.3 000:15				
		Total I	Labor Hours:	0.3 0:15
Parts Used				
Qty Part#	Description	Serial#	Cost	Sub Total
1 34-0428070-64	White Position Light (A508-28)		22.8	0 22.80
Technician Release		Work Order Totals		
Buy Back Test FLT	Tech Signature:	Tech#:	Labor	18.75
			Parts	22.80
Maintenance Release		TOTAL:	41.55	
The aircraft, airframe, aircraft engine, propeller or appliance identified above, was inspected and repaired in accordance with current Regulations of the Federal Aviation Administration and is approved for return to service. Pertinent details of the repair/inspection are on file at the Repair Station under this Work Order.		Preliminary / Hidden Inspection Release		
Data	Signad		Date:	
Date: Signed: WMU FAA CertificatedRepair Station JX8R258Q . 237 N Helmer Road, Battle Creek, MI 49037		Inspector:		