WO#: 2019 01554

191JG

1699

Cirrus

SR-20

5843.3

Signed:

WMU FAA CertificatedRepair Station JX8R258Q

Reg#:

MFG:

Model:

A/C Tach Time:

AC S/N:

Work Order

Western Michigan University College of Aviation

FAA CertificatedRepair Station JX8R258Q 237 N Helmer Road, Battle Creek, MI 49037

Date Started: 09/14/19 Date Completed: 09/25/19

5843.3 A/C Total Time: RT Eng. T.T.:

LT Eng T.T.: 977.1 LT Prop T.T.: 3105.9

RT Prop. T.T.

Inspector:

| Description of Work to be Performed | | | | | |
|---|----------------------|--------------------------------|---------|--|----------------|
| 1) ETA | squawk: white nav li | ght is out on the left side | | | |
| Maintenance/Repairs Performed | | | | | |
| 1) ETA squawk: white nav light is out on the left side Airframe: | | | | | |
| Installed new LH white position light bulb. | | | | | |
| Labor | | | | | |
| Nathan St | tewart 0.5 000:30 | | | | |
| | | | | | 0:30 |
| Parts Used | | | | | |
| Qty | Part# | Description | Serial# | Cost | Sub Total |
| 1 | 34-0428070-64 | White Position Light (A508-28) | | 37.04 | 37.04 |
| Technician Release | | | | Work Order Totals | |
| Buy Back ☐ Test FLT ☐ Tech Signature: Tech#: | | | | Labor Parts | 37.50 37.04 |
| Maintenance Release | | | | TOTAL: | 74.54 |
| The aircraft, airframe, aircraft engine, propeller or appliance identified above, was inspected and repaired in accordance with current Regulations of the Federal Aviation Administration and is approved for return to service. Pertinent details of the repair/inspection are on file at the Repair Station under this Work Order. | | | | Preliminary / Hidden Inspection Release Date: | |

. 237 N Helmer Road, Battle Creek, MI 49037