WO#: 2012 00461

91SA

1710

Cirrus

SR-20

2817.3

Reg#:

MFG:

Model:

A/C Tach Time:

AC S/N:

Work Order

## **Western Michigan University College of Aviation**

FAA CertificatedRepair Station JX8R258Q 237 N Helmer Road, Battle Creek, MI 49037

Date Started: 04/03/12 Date Completed: 04/04/12

A/C Total Time: 2817.3 RT Eng. T.T.: RT Prop. T.T.

LT Eng T.T.: 828.4 LT Prop T.T.: 2825.4

## **Description of Work to be Performed**

1) 116	ap retraction difficultie	:5				
Maintenance/Repairs Performed						
1) flap	retraction difficulties					
Rep.	laced flap up and down re	elays. Ops check good.				
		Labor				
Dhru Pat	tel 0.5 000:30	330 2				
						0:30
		Parts Used				
Qty	Part#	Description	Serial#		Cost	Sub Total
2	50288-001	Relay, Flap or Circuit Panel (Alt P/N V23234-A0004-X051)			14.63	29.26
Technician Release				Work Order Totals		
Buy Back Test FLT Tech Signature: Tech#:				La	abor	30.00
		· · · · · · · · · · · · · · · · · · ·		Pá	arts	29.26
Maintenance Release				TOTAL:		59.26
The aircraft, airframe, aircraft engine, propeller or appliance identified above, was inspected and repaired in accordance with current Regulations of the Federal Aviation Administration and is approved for return to service. Pertinent details of the repair/inspection are on file at the Repair Station under this Work Order.				Preliminary / Hidden Inspection Release		
Da	ate:			Da		
WMU FAA CertificatedRepair Station JX8R258Q . 237 N Helmer Road, Battle Creek, MI 49037					pector:	