WO#: 2018 00933

191JG

1699

Cirrus

SR-20

5148.7

Reg#:

MFG:

Model:

A/C Tach Time:

AC S/N:

Work Order

## Western Michigan University **College of Aviation**

FAA CertificatedRepair Station JX8R258Q 237 N Helmer Road, Battle Creek, MI 49037

06/21/18 Date Started: Date Completed: 06/29/18

A/C Total Time: 5148.7

RT Eng. T.T.: RT Prop. T.T.

LT Eng T.T.: 273.6 LT Prop T.T.: 2402.4

Description of Work to be Performed				
1) LH rear position bulb.				
	Maintenance/Repairs Pe	rformed		
1) LH rear position bulb. Airframe:				
Replaced LH rear position b	ulb.			
	Labor			
Brian Schmidt 0.5 000:30				
				0:30
	Parts Used			
Qty Part#	Description	Serial#	Cost	Sub Total
1 34-0428070-64	White Position Light (A508-28)		22.02	2 22.02
Technician Release			Work Order Totals	
Buy Back ☐ Test FLT ☐ Tech Signature: Tech#:			Labor Parts	30.00 22.02
Maintenance Release			TOTAL:	52.02
The aircraft, airframe, aircraft engine, propeller or appliance identified above, was inspected and repaired in accordance with current Regulations of the Federal Aviation Administration and is approved for return to service. Pertinent details of the repair/inspection are on file at the Repair Station under this Work Order.		Preliminary / Hidden Inspection Release		
Date: Signed: WMU FAA CertificatedRepair Station JX8R258Q . 237 N Helmer Road, Battle Creek, MI 49037			Date:	