

HPE Cray EX Series System Administration with HPE Performance Cluster Manager

Lab exercise system health

1. Review health checks and health alerts:

```
cm health check -h
cm health check -l
cm health check -o -n <node or group of nodes> cpuchk
cm health check -o -n <node or group of nodes> memchk
cm health alert -h
cm health alert -s
cm health alert -g
cm health alert -c
cm health alert query
```

- 2. Select a few additional health checks and run them.
- 3. Skim the HPE Performance Cluster Manager Administration Guide sections:

Monitoring cluster health with the cm health check command	255
Verifying and modifying the cluster health check configuration filefile	256
cm health check command interoperability with other products	257
Using the cm health check command	257
Specific health checks	258
Integrating cluster health check and Slurm	
Integrating cluster health check and Altair PBS Professional	
Regenerating new node configuration files	
Adding new health checks	
Modifying the functionality of a health check	
Modifying the parameters of a health check	
Preventing a health check from running	
Gluster file system health checks	
Monitoring alerts with the cm health alert command	
cm health alert command examples	274
Managing the alert life cycle	277
Configuring ElastAlert email alerts	278
Alert types	280
Enabling the ${ m cron}$ job for monitoring InfiniBand fabricfabric fabric fab	283
Enabling the cron job for monitoring the Gluster file system	283
Editing the baseline file manually	
Displaying receive time for alerts in the user time zone	
HPE Slingshot alerts	
Specifying HPE Slingshot alert levels in the . yaml files files	288

This complete lab exercise system health.