Report Generated by Test Manager

Title: TCF_IsCalc MIL Test Report

Author:

Date: 19-Dec-2021 09:50:45

Test Environment

Platform: PCWIN64 MATLAB: (R2020a)

Summary

Name Outcome Duration (Seconds)

IsCalc

Test Result Information

Result Type: Test Suite Result

Parent: None

Start Time: 2021-12-18 19:24:01 End Time: 2021-12-18 19:24:03 Outcome: Total: 1, Passed: 1

Test Suite Information

Name: IsCalc

Aggregated Coverage Results

Analyzed Model	Sim Mode	Complexity	Execution
SWC_TCF/SWC_TCF_1ms_sys/PwrTrqCalcProc/IsCalc	Normal	1	100%

Back to Report Summary

EI09_SWUT_MIL_IsCalc_01

Test Result Information

Result Type: Test Case Result

Parent: <u>IsCalc</u>

Start Time: 2021-12-18 19:24:01 End Time: 2021-12-18 19:24:03

Outcome: Passed

Test Case Information

Name: EI09_SWUT_MIL_IsCalc_01

Type: Baseline Test

Baseline Name: IsCalc

Baseline File: E:\EI09_Project\ei09\03_Controller_Models\02_Pla

 $tform_Models \\ \label{local_platform} I_Platform \\ models \\ \label{local_platform} FS \\ \label{local_platform} TCF_V2$

\TestCase_TCF.xlsx

Input Data


Input Information

External Input Na EI09_SWUT_MIL_IsCalc_01

me:


Name	Data Type	Units	Sample Time	Interp	Sync	Link
	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		L			to Plot
TRSP_iU	single		 	zoh	union	<u>Link</u>
TRSP_iV	single		 	zoh	union	<u>Link</u>
TRSP_iW	single			zoh	union	<u>Link</u>

Name	Data Type	Units	Sample Time	Interp	Sync
TRSP_iU	single			zoh	union
TRSP_iV	single			zoh	union



Back to Report SummaryBack to Signal Summary

Name	Data Type	Units	Sample Time	Interp	Sync
TRSP_iW	single			zoh	union



Back to Report SummaryBack to Signal Summary

Simulation

System Under Test Information

Model: SWC_TCF

Harness: SWC_TCF_Harness_IsCalc

Harness Owner: SWC_TCF/SWC_TCF_1ms_sys/PwrTrqCalcProc/IsC

alc

Simulation Mode: normal

Override SIL or PIL Mod 0

e:

Configuration Set: Configuration 1

External Input Name: EI09_SWUT_MIL_IsCalc_01

External Input File: E:\EI09_Project\ei09\03_Controller_Models\02_Pla

 $tform_Models \verb|\01_Platformmodels\\| FS\\| TCF\\| TCF_V2$

\TestCase_TCF.xlsx

Start Time: 0 Stop Time: 0.01

Checksum: 3160359560 1536353125 700594633 3539679768

Simulink Version: 10.1 Model Version: 1.1

Model Author: dongliyuan

Date: Mon Jul 26 16:49:43 2021

User ID: dongliyuan

Model Path: E:\EI09_Project\ei09\03_Controller_Models\02_Pla

tform_Models\01_Platformmodels\FS\TCF\TCF_V2

\SWC TCF.slx

Machine Name: MC-ZHANGJUNRENB Solver Name: FixedStepDiscrete

Solver Type: Fixed-Step Fixed Step Size: 0.0001


Simulation Start Time: 2021-12-18 19:24:01 Simulation Stop Time: 2021-12-18 19:24:02

Platform: PCWIN64

Simulation Output

Name	Data Type	Units	Sample Time	Interp	Sync	Link to Plot
TCF_Is	single			zoh	union	<u>Link</u>

Name	Data Type	Units	Sample Time	Interp	Sync
TCF_Is	single			zoh	union



Back to Report SummaryBack to Signal Summary

Simulation Logs:

Simulation stopped at '0.01' because there is no input data after this time point.

Back to Report Summary

Test Logs:

Some of the signals specified in baseline criteria were not found in the file located at 'E:\EI09_Project\ei09\03_Controller_Models\02_Platform_Models \01_Platformmodels\FS\TCF\TCF_V2\TestCase_TCF.xlsx':

Name: TCF_Is Data Source: ds.getElement(1).Values.Data You may have updated the baseline file with new set of signals. Try to add the baseline file again to the test to get the updated signal list.

Back to Report Summary