Split DLMS

Woody Wu

November 16, 2016

${\it Case}\ 1$

Case 1	
Ch.1 DLMS 2016-11-01T00:20:21.813CST CU-Z62 on E850#50506421.H03	Ch.2 DLMS 2016-11-01T00:20:21.772CST RS485 on E850#50506421.H03
> 7EA04700 0272FB61 BA0A48E6 E6000501 > 04627801 02040204 12000809 06000001 > 0000FF0F 02120000 090C07E0 0A1FFF16 > 14010080 0000090C 07E00B01 FF001400 > 00800000 0100D854 7E < 7EA04B61 000272FB DA1E21E6 E7000C01 < 00020C09 0C07E00B 0102000F 00FF8000 < 00060081 00041400 00000000 14B9E614 < 00000000 0000172B 14000000 00000129 < 3B140000 00000000 25D7E259 7E	
Case 2 Ch.1 DLMS 2016-11-14T05:10:02.118CST CU-Z62 on E850#51500165 ver: H03	Ch.2 DLMS 2016-11-14T05:10:02.219CST RS485 on E850#51500165 ver: H03
> 7EA04700 02121B61 962133E6 E6000501 > 04627801 02040204 12000809 06000001 > 0000FF0F 02120000 090C07E0 0B0EFF05 > 09010080 0000090C 07E00B0E FF050A00 > 00800000 0100FC2A 7E < 7EA04B61 0002121B 98DCACE6 E7000C01 < 00021A09 0C07E00B 0E01050A 00FF8000 < 00060081 00041400 00000000 00004714 < 00000000 0000536B 14000000 00000005 < 2E140000 00000003 85B8BF28 7E	> 7EA04700 02121B61 7019B1E6 E6000501 > 04627801 02040204 12000809 06000001 > 0000FF0F 02120000 090C07E0 0B0EFF05 > 09010080 0000090C 07E00B0E FF050A00 > 00800000 0100FC2A 7E <pre> </pre> <pre> < 7EA0C861 0002121B 36DBCEE6 E7000C01 < 00010114 00000000 00000526 14000000 < 00000000 B7140000 0000003 85011400 < 00000000 00000814 00000000 00000000 < 14000000 00000000 0C140000 00000000 < 002F1400 00000000 0C140000 00000000 < 0000000 1EA31400 0000000 0194A14 < 00000000 1EA31400 0000000 00194A14 < 00000000 00000000 14000000 00000082 < 88140000 00000000 C6B41400 00000000 < 00A22814 00000000 00000000 14000000 < 000A22814 00000000 00000000 14000000 < 00000076 46140000 00000000 83E21400</pre>

Case 3

Ch.1 DLMS 2016-11-16T00:00:57.532CST CU-B2 on E850#51500165.H03

- > 7EA04700 0272FB61 D05684E6 E6000501
- > 04627801 02040204 12000809 06000001
- > 0000FF0F 02120000 090C07E0 0B10FF00
- > 00000080 0000090C 07E00B10 FF000001
- > 00800000 01004BE6 7E
- < 7EA01461 000272FB 3C1DC8E6 E7000C01
- < 000102EB D27E

Ch.2 DLMS 2016-11-16T00:00:57.724CST RS485 on E850#51500165.H03

- > 7EA04700 0272FB61 9052C6E6 E6000501
- > 04627801 02040204 12000809 06000001
- > 0000FF0F 02120000 090C07E0 0B10FF00
- > 00000080 0000090C 07E00B10 FF000001
- > 00800000 01004BE6 7E
- < 7EA0C061 000272FB 389D15E6 E7000C01
- < 00020C09 0C07E00B 10030000 00FF8000
- < 00060081 00041400 00000000 14B9E614
- < 00000000 0000172B 14000000 00000129
- < 3B140000 00000000 25D70500 00045605
- < 00000000 05000000 00050000 00000500
- < 00000005 00000000 020C090C 07E00B10
- < 03000000 FF800000 06000900 04140000
- < 00000014 B9E61400 00000000 00172B14
- < 00000000 0001293B 14000000 00000025
- < D7050000 04560500 00000005 00000000
- < 05000000 00050000 00000500 00000051
- < 587E