How to Dock Devices to USB

Prerequisites

To accomplish this process, you will need:

- WP Securebook
- Black (USB) Securebook Docking Station
- USB Device

To Access a USB devices with a Securebook, follow these steps:

- 1. Power Off the Securebook
- 2. Dock the Securebook onto the Black Docking Station




Note: If the Securebook is correctly situated on the docking station, A green light will light up on the side. If there is no light, the Securebook could be improperly mounted, powered off, or even be dead (0% power).

- 3. Power On the Securebook
- 4. Log in to an account
- 5. Plug the desired USB device into the Black USB Dock



- 6. Open the Document Explorer
- 7. Select the USB device from the pane on the left



Users are not limited to using a singular Black Docking Station. Should the need arise, the user can repeat the steps above on an entirely different Black Docking Station and achieve the same results. *Note*: For best results, make sure the Securebook is Turned Off when docking to a Black Docking Station.