




Capacitor C99 is assembled on the waste part of the panel, outside the PCB. Its aim is that the horizontal pins of the connector lean on it during the electronic assembly process, so the connector keeps its right position. After the de-paneling process, C99 is not to be found on the circuit



TOP



## BOTTOM



For details see LK0142-1-

geänd. changed	26/03/2020	TOR	C0121072	Device added for support the connector. Minor changes for cost savings.					
Datum	Date	Name	Name	TAE-Nr.	EC-No.	Aenderungsbeschreibung	Change-description		
Darf nicht manuell geändert werden  May not be changed manually		Datum Date	Name Name	Massstab	Scale	Dok. Nummer	Doc. number	Aend. stand Rev. level	
	Erstellt Drawn	09.09.2017	L. M. Tortosa	none		DOC02045393		06	
	Gepr. Checked	10.01.2017	I. Ameijeiras	Oberflaeche	Surface Coating				
	Norm. Appr.	11.01.2017	D. Rodriguez	--		Klassifikation	Classification	Dok. typ	Doc.type
	Leopold Kostal GmbH & Co. KG Automobil - Elektrik Luedenscheid			Allgemeintoleranz	General Tolerance	PCBSTUFF			
				DIN ISO 2768 (f)					
	Projekt-Nr. Project-No.	P07520		Halbzeug	Material Form	Variants 12 & 16 10" Basic & 10" Electric			
	D-Pflicht Documentation			Werkstoff	Material	Teile Nr.	Part No.	Aend. stand Rev. level	
				--		12025971		07	
	Schutzvermerk nach LK0029 beachten All rights reserved see LK 0029			Artikel Nr.	Article No.	Blatt Nr. Sheet No.	1 of 1		
			08	FMUX P2					