



Capacitor C99 is assembled on the waste part of the panel, outside the PCB. Its aim is that the horizontal pins of the connector lean on it during the electronic assembly process, so the connector keeps its right position. After the de-paneling process, C99 is not to be found on the circuit.



TOP



BOTTOM



For details see LK0142-1-1

geänd. changed	21/04/2023	TOR	CO148385	Replacement of the SBC: TJA1028TK from NXP is used				
	Datum  Erstellt/ Drawn	Date  Name Datum Date	Name Name	TAE-Nr. 09.01.2018	EC-No. L. M. Tortosa	Aenderungsbeschreibung  Massstab none		Change-description  Dok. Nummer DOC02045309
Darf nicht manuell // geändert werden  May not be changed manually	Gepr. Checked	10.01.2018	I. Ameijeiras	Oberflaeche --	Scale Surface Coating	Dok. Number 08		
	Norm. Appr.	11.01.2018	D. Rodriguez	Allgemeintoleranz Leopold Kostal GmbH & Co. KG Automobil - Elektrik Luedenscheid	General Tolerance DIN ISO 2768 (f)	Klassifikation PCBSTUFF	Dok. typ Part Name/Doc.title	Doc. type
	Projekt-Nr. Project-No.	P07520		Halbzeug --	Material Form --		Variant 1 RCE basic	
	D-Pflicht Documentation		Werkstoff --	Material --	Teile Nr. 10343644	Aend. stand Rev. level 09		
	Schutzvermerk nach LK0029 beachten All rights reserved see LK 0029		SI 08	Artikel Nr. 10341315	Article No. Blatt Nr. Sheet No. 1 von of 1			