



Capacitor C99 is assembled on the waste part of the panel, outside the PCB. Its aim is that the horizontal pins of the connector lean on it during the electronic assembly process, so the connector keeps its right position. After the de-paneling process, C99 is not to be found on the circuit.



TOP



BOTTOM



For details see LK0142-1-1

geänd. changed	07/01/2020	TOR	C0121072	Device added for support the connector. Minor changes for cost saving								
	Datum Date	Name Name	TAE-Nr. EC-No.	Änderungsbeschreibung Change-description								
Darf nicht manuell // geändert werden May not be changed manually		Datum Date	Name Name	Massstab Scale	none	Dok. Nummer Doc. number	DOC02045309	Aend. stand Rev. level	06			
	Erstellt Drawn	09.01.2018	L. M. Tortosa	Oberfläche Surface Coating	--							
	Gepr. Checked	10.01.2018	I. Ameijeiras									
	Norm Apr.	11.01.2018	D. Rodriguez	Allgemeintoleranz General Tolerance		Klassifikation Classification		Dok. typ Doc. type		PCBSTUFF		
	Leopold Kostal GmbH & Co. KG Automobil - Elektrik Luedenscheid			DIN ISO 2768 (f)		Benennung/Titel Part Name/Doc.title						
	Projekt-Nr. Project-No.	P07520		Halbzeug Material Form	--	Variant 1 RCE basic						
	D-Pflicht Documentation			Werkstoff Material	--	Teile Nr. Part No.	10343644			Aend. stand Rev. level		
	Schutzvermerk nach LK0029 beachten All rights reserved see LK 0029			Artikel Nr. Article No.			Blatt Nr. Sheet No.	1	von of	07		
				10341315				1				