



Capacitor C99 is assembled on the waste part of the panel, outside the PCB.
Its aim is that the horizontal pins of the connector lean on it during
the electronic assembly process, so the connector keeps its right position.
After the de-paneling process, C99 is not to be found on the circuit.



TOP



BOTTOM



For details see LK0142-1-1

geoend. changed	29/03/2022	TOR	C0140712	Change of plastic material in main connector	Change-description
	Datum Date	Name Name	TAE-Nr. EC-No.	Aenderungsbeschreibung Change description	Dok. Nummer Doc.number
Erstellt/ Drawn	09.01.2018	L. M. Tortosa		Massstab Scale none	
Gepr./ Checked	10.01.2018	I. Ameijeiras		Oberflaeche Surface Coating --	
Norm/ Appr.	11.01.2018	D. Rodriguez		Allgemeintoleranz General Tolerance DIN ISO 2768 (f)	
		Leopold Kostal GmbH & Co. KG Automobil - Elektrik Luedenscheid			
Projekt-Nr. Project-No.	P07520			Halbzeug Material Form --	
D-Pflicht Documentation				Werkstoff Material --	
			SI	Artikel Nr. Article No.	Teile Nr. Part No.
		All rights reserved see LK 0029	08	FMUX P2	12025968
					Aend. stand Rev.level 08
					Blatt Nr. 11 von 1 1
					Sheet No.