



Capacitor C99 is assembled on the waste part of the panel, outside the PCB. Its aim is that the horizontal pins of the connector lean on it during the electronic assembly process, so the connector keeps its right position. After the de-paneling process, C99 is not to be found on the circuit



TOP



BOTTOM



For details see LK0142-1-1

geänd. changed Darf nicht manuell // geändert werden May not be changed manually	29/03/2022		TOR	C0140712		Change of plastic material in main connector											
	Datum Date	Date	Name Name	TAE-Nr. EC-No.	Änderungsbeschreibung			Change-description									
			Datum Date	Name Name	Massstab	Scale	Dok. Nummer	Doc. number	Aend. stand	Rev. level							
	Erstellt/ Drawn	09.01.2018	L. M. Tortosa		none				DOC02045319	07							
	Gepr./ Checked	10.01.2018	I. Ameijeiras		Oberfläche	Surface Coating											
	Norm/ Appr.	11.01.2018	D. Rodriguez		--		Klassifikation	Classification	Dok. typ	Doc.type							
	Leopold Kostal GmbH & Co. KG Automobil - Elektrik Luedenscheid				Allgemeintoleranz	General Tolerance	PCBSTUFF										
					DIN ISO 2768 (f)												
	Projekt-Nr. Project-No.	P07520			Halbzeug	Material Form	Variant 4 7 th Basic										
	D-Pflicht Documentation				Werkstoff	Material	Teile Nr.	Part No.	Aend. stand Rev. level	08							
Schutzvermerk nach LK0029 beachten All rights reserved see LK 0029					SI	Artikel Nr.	Article No.	12025966									
					08	10341318		Blatt Nr. Sheet No.	1 von of	1							