




Capacitor C99 is assembled on the waste part of the panel, outside the PCB.
Its aim is that the horizontal pins of the connector lean on it during
the electronic assembly process, so the connector keeps its right position.
After the de-paneling process, C99 is not to be found on the circuit.



TOP



BOTTOM



For details see LK0142-1-1

<i>Darf nicht manuell // geändert werden</i> May not be changed manually	geänd. changed	07/01/2020	TOR	C0121072	Device added for support the connector. Minor changes for cost saving		
	Datum Date	Name Name	TAE-Nr. Name	EC-No. Name	Aenderungsbeschreibung Change-description		
	Erstellt/ Drawn	09.01.2018	L. M. Tortosa		Maßstab Scale	Dok. Nummer Doc.number	Aend. stand/ Rev.level
	Gepr./ Checked	10.01.2018	I. Ameijiras		oberfläche Surface Coating		
	Norm/ Appr.	11.01.2018	D. Rodriguez		--		
	Leopold Kostal GmbH & Co. KG Automobil - Elektrik Luedenscheid			Allgemeintoleranz General Tolerance	DIN ISO 2768 (f)	Klassifikation Classification	Dok. typ Doc.type
	Projekt-Nr. Project-No.	P07520		Halbzeug Material Form	--	Benennung/Titel Part Name/Doc.title	Variant 4
	D-Pflicht Documentation			Werkstoff Material	--	Teile Nr. Part No.	7' Basic
	Schutzvermerk nach LK0029 beachten All rights reserved see LK 0029		S1	Artikel/ Nr. Article No.			
			08	10341318		Blatt Nr. Sheet No.	1 von 1