

Pin Map

Pin Name	Pin	Pin Name	Pin
DIR	1	OE	19
A1	2	A2	3
A3	4	A4	5
A5	6	A6	7
A7	8	A8	9
B1	18	B2	17
B3	16	B4	15
B5	14	B6	13
B7	12	B8	11

Global Parameters

Parameter	Value
VCC Pin	20
GND Pin	10
VCC Voltage	5
Input Low	0.8
Input High	2
Output Low	0.33
Output High	3.84

Tests: IC PASS 19/19

$A=0, DIR=H, OE=L \rightarrow B=0$: PASS

[illegible]

A=1, DIR=H, OE=L -> B=1: PASS

Inputs			Outputs/Results															
A8, A7, A6, A5, A4, A3, A2, A1	DIR	OE	B8		B7		B6		B5		B4		B3		B2		B1	
0b00000001	H	L	0	0.0 (0)	0	0.0 (0)	0	0.0 (0)	0	0.0 (0)	0	0.0 (0)	0	0.0 (0)	0	0.0 (0)	1	4.86 (1)

A=2, DIR=H, OE=L -> B=2: PASS

Inputs			Outputs/Results															
A8, A7, A6, A5, A4, A3, A2, A1	DIR	OE	B8		B7		B6		B5		B4		B3		B2		B1	
0b00000010	H	L	0	0.0 (0)	0	0.0 (0)	0	0.0 (0)	0	0.0 (0)	0	0.0 (0)	0	0.0 (0)	1	4.86 (1)	0	0.0 (0)

A=4, DIR=H, OE=L -> B=4: PASS

Inputs			Outputs/Results															
A8, A7, A6, A5, A4, A3, A2, A1	DIR	OE	B8		B7		B6		B5		B4		B3		B2		B1	
0b00000100	H	L	0	0.0 (0)	0	0.0 (0)	0	0.0 (0)	0	0.0 (0)	0	0.0 (0)	1	4.85 (1)	0	0.0 (0)	0	0.0 (0)

A=8, DIR=H, OE=L -> B=8: PASS

Inputs			Outputs/Results															
A8, A7, A6, A5, A4, A3, A2, A1	DIR	OE	B8		B7		B6		B5		B4		B3		B2		B1	
0b00001000	H	L	0	0.0 (0)	0	0.0 (0)	0	0.0 (0)	0	0.0 (0)	1	4.86 (1)	0	0.0 (0)	0	0.0 (0)	0	0.0 (0)

A=16, DIR=H, OE=L -> B=16: PASS

Inputs			Outputs/Results															
A8, A7, A6, A5, A4, A3, A2, A1	DIR	OE	B8		B7		B6		B5		B4		B3		B2		B1	
0b00010000	H	L	0	0.0 (0)	0	0.0 (0)	0	0.0 (0)	1	4.86 (1)	0	0.0 (0)	0	0.0 (0)	0	0.0 (0)	0	0.0 (0)

A=32, DIR=H, OE=L -> B=32: PASS

Inputs			Outputs/Results															
A8, A7, A6, A5, A4, A3, A2, A1	DIR	OE	B8		B7		B6		B5		B4		B3		B2		B1	
0b00100000	H	L	0	0.0 (0)	0	0.0 (0)	1	4.86 (1)	0	0.0 (0)	0	0.0 (0)	0	0.0 (0)	0	0.0 (0)	0	0.0 (0)

A=64, DIR=H, OE=L -> B=64: PASS

Inputs			Outputs/Results															
A8, A7, A6, A5, A4, A3, A2, A1	DIR	OE	B8		B7		B6		B5		B4		B3		B2		B1	
0b01000000	H	L	0	0.0 (0)	1	4.86 (1)	0	0.0 (0)	0	0.0 (0)	0	0.0 (0)	0	0.0 (0)	0	0.0 (0)	0	0.0 (0)

A=128, DIR=H, OE=L -> B=128: PASS

Inputs			Outputs/Results															
A8, A7, A6, A5, A4, A3, A2, A1	DIR	OE	B8		B7		B6		B5		B4		B3		B2		B1	
0b10000000	H	L	1	4.85 (1)	0	0.0 (0)	0	0.0 (0)	0	0.0 (0)	0	0.0 (0)	0	0.0 (0)	0	0.0 (0)	0	0.0 (0)

B=1, DIR=L, OE=L -> B=1: PASS

Inputs			Outputs/Results															
B8, B7, B6, B5, B4, B3, B2, B1	DIR	OE	A8		A7		A6		A5		A4		A3		A2		A1	
0b00000001	L	L	0	0.0 (0)	0	0.0 (0)	0	0.0 (0)	0	0.0 (0)	0	0.0 (0)	0	0.0 (0)	0	0.0 (0)	1	4.86 (1)

B=2, DIR=L, OE=L -> B=2: PASS

Inputs			Outputs/Results																	
B8, B7, B6, B5, B4, B3, B2, B1			DIR	OE	A8		A7		A6		A5		A4		A3		A2		A1	
0b00000010			L	L	0	0.0 (0)	0	0.0 (0)	0	0.0 (0)	0	0.0 (0)	0	0.0 (0)	0	0.0 (0)	1	4.86 (1)	0	0.0 (0)

B=4, DIR=L, OE=L -> B=4: PASS

Inputs			Outputs/Results															
B8, B7, B6, B5, B4, B3, B2, B1	DIR	OE	A8		A7		A6		A5		A4		A3		A2		A1	
0b00000100	L	L	0	0.0 (0)	0	0.0 (0)	0	0.0 (0)	0	0.0 (0)	0	0.0 (0)	1	4.86 (1)	0	0.0 (0)	0	0.0 (0)

B=8, DIR=L, OE=L -> B=8: PASS

Inputs			Outputs/Results															
B8, B7, B6, B5, B4, B3, B2, B1	DIR	OE	A8		A7		A6		A5		A4		A3		A2		A1	
0b00001000	L	L	0	0.0 (0)	0	0.0 (0)	0	0.0 (0)	0	0.0 (0)	1	4.86 (1)	0	0.0 (0)	0	0.0 (0)	0	0.0 (0)

B=16, DIR=L, OE=L -> B=16: PASS

Inputs			Outputs/Results															
B8, B7, B6, B5, B4, B3, B2, B1	DIR	OE	A8		A7		A6		A5		A4		A3		A2		A1	
0b00010000	L	L	0	0.0 (0)	0	0.0 (0)	0	0.0 (0)	1	4.85 (1)	0	0.0 (0)	0	0.0 (0)	0	0.0 (0)	0	0.0 (0)

B=32, DIR=L, OE=L -> B=32: PASS

Inputs			Outputs/Results															
B8, B7, B6, B5, B4, B3, B2, B1	DIR	OE	A8		A7		A6		A5		A4		A3		A2		A1	
0b00100000	L	L	0	0.0 (0)	0	0.0 (0)	1	4.86 (1)	0	0.0 (0)	0	0.0 (0)	0	0.0 (0)	0	0.0 (0)	0	0.0 (0)

B=64, DIR=L, OE=L -> B=64: PASS

Inputs			Outputs/Results															
B8, B7, B6, B5, B4, B3, B2, B1	DIR	OE	A8		A7		A6		A5		A4		A3		A2		A1	
0b01000000	L	L	0	0.0 (0)	1	4.85 (1)	0	0.0 (0)	0	0.0 (0)	0	0.0 (0)	0	0.0 (0)	0	0.0 (0)	0	0.0 (0)

B=128, DIR=L, OE=L -> B=128: PASS

Inputs			Outputs/Results															
B8, B7, B6, B5, B4, B3, B2, B1	DIR	OE	A8		A7		A6		A5		A4		A3		A2		A1	
0b10000000	L	L	1	4.85 (1)	0	0.0 (0)	0	0.0 (0)	0	0.0 (0)	0	0.0 (0)	0	0.0 (0)	0	0.0 (0)	0	0.0 (0)

A=0, B=128, DIR=X, OE=H -> A=0, B=128: PASS

			Outputs/Results																					
B4, B3, B2, B1	DIR	OE	A8		A7		A6		A5		A4		A3		A2		A1		B8		B7		B6	
0000	X	H	0	0.0 (0)	0	0.0 (0)	0	0.0 (0)	0	0.0 (0)	0	0.0 (0)	0	0.0 (0)	0	0.0 (0)	0	0.0 (0)	1	4.86 (1)	0	0.0 (0)	0	0.0 (0)

A=170, B=85, DIR=X, OE=H -> A=170, B=85: PASS

			Outputs/Results																					
B3, B2, B1	DIR	OE	A8		A7		A6		A5		A4		A3		A2		A1		B8		B7		B6	
-	X	H	1	4.86 (1)	0	0.0 (0)	1	4.86 (1)	0	0.0 (0)	1	4.85 (1)	0	0.0 (0)	1	4.86 (1)	0	0.0 (0)	0	0.0 (0)	1	4.85 (1)	0	0.0 (0)