

ARM® Cortex®-M23 32-bit Microcontroller

NuMicro® Family M2L31 Series BSP Revision History

The information described in this document is the exclusive intellectual property of Nuvoton Technology Corporation and shall not be reproduced without permission from Nuvoton.

Nuvoton is providing this document only for reference purposes of NuMicro® microcontroller and microprocessor based system design. Nuvoton assumes no responsibility for errors or omissions.

All data and specifications are subject to change without notice.

For additional information or questions, please contact: Nuvoton Technology Corporation.

www.nuvoton.com

Revision 3.03.000 (Released 2026-06-02)

1. Change CMSIS from rev. 5.1.1 to rev. 6.1.0
2. Send NAK instead of 0 to fix host can't sleep issue
3. Fix the UART clock select
4. Correct the IFA Timer PWM counter define
5. Add Trim sample code
6. Add the VSCode project to the bsp
7. Update MIRC Trim sample code
8. Update TimerPWM sample code
9. Add a check for the STOP bit when I2C transmission is complete.
10. Update PD source code for more close to CTS requirements.
11. Update UTPD Libraries and Sample Code for Certification
12. Adding NuMaker_PD30_DRP Sample Code for Battery Charger and Synchronize ...
13. Modify Timer Driver
14. Update TK Tool
15. Update PD Libraries and related Sample Code
16. Move the HIDTransferTest tool to Tool folder and add version to the tool
17. Remove obsolete DFU tools and add README for usage instructions
18. PD: Modify library and headers to support changing the requested PDO
19. Add SBOM components and licensing information for Nuvoton software
20. Modify the command shell to provide a request PDO command and remove some ...
21. USB PD: Fix typo errors in file-usb_pd_policy.c

Revision 3.02.000 (Released 2024-12-17)

22. Updated sample code for M2L31 with only 4 KB SRAM.
23. Updated setting order of scatter-gather mode for PDMA and LPPDMA driver.
24. Updated EADC driver for ADC calibration.
25. Updated USB device sample code for V_{Bus} detect.
26. Removed LPM function from USB device sample code.
27. Changed PLL frequency setting from 240 MHz to 144 MHz for USB device samples.
28. Added RMC_DummyReadCID function for RRAM write after wake-up from Power-down mode.
29. Added I²C error handling when error flag asserted.
30. Added channel reset macro for PDMA and LPPDMA driver.
31. Minor changes for sample code.
32. Minor bug fix.

Revision 3.01.000 (Released 2024-05-16)

1. Removed Power Level 2 from SYS driver and SYS_PowerMode sample code.
2. Removed POR disable on Startup file for GCC and IAR.
3. Updated LPADC and EADC driver to enable ADC decoding with extra one cycle to improve ADC accuracy.
4. Updated I²C driver to support 10 bits salve address mode.
5. Added 3-wire SPI interface Macro for SPI and LPSPI drivers.
6. Added CANFD CAN mode samples.
7. Minor changes for sample code.
8. Minor bug fix.

Revision 3.00.000 (Released 2024-01-15)

1. Primary release version.

Important Notice

Nuvoton Products are neither intended nor warranted for usage in systems or equipment, any malfunction or failure of which may cause loss of human life, bodily injury or severe property damage. Such applications are deemed, "Insecure Usage".

Insecure usage includes, but is not limited to: equipment for surgical implementation, atomic energy control instruments, airplane or spaceship instruments, the control or operation of dynamic, brake or safety systems designed for vehicular use, traffic signal instruments, all types of safety devices, and other applications intended to support or sustain life.

All Insecure Usage shall be made at customer's risk, and in the event that third parties lay claims to Nuvoton as a result of customer's Insecure Usage, customer shall indemnify the damages and liabilities thus incurred by Nuvoton.

*Please note that all data and specifications are subject to change without notice.
All the trademarks of products and companies mentioned in this datasheet belong to their respective owners.*