
Tip vertical change
s050 positive
s050 negative
s070 positive
s070 negative
Z change (mm)
0
1
2
3
4
5
6
0
1
2
3
4
Time (s)