



## HIGH-END AUTOMOTIVE LLC.

"Quality Work At A Reasonable Price"

1933 Youngsville Highway, Youngsville, LA 70592

Phone: (337) 268-5101

FAX: (337) 268-5104

Workfile ID:  
PartsShare:

02cac650  
62rk7Z

Federal ID:

20-3798217

### Preliminary Estimate

**RO Number: 13493**

Written By: MICHELLE LAVERGNE

Insured: MCNARY NURSERY

Policy #:

Claim #:

Type of Loss:

Date of Loss:

Days to Repair: 0

Point of Impact: 11 Left Front

**Owner:**

MCNARY NURSERY  
12149 HWY 165 SOUTH  
GLENMORA, LA 71433

**Inspection Location:**

HIGH-END AUTOMOTIVE LLC.  
1933 Youngsville Highway  
Youngsville, LA 70592  
Repair Facility  
(337) 268-5101 Business

**Insurance Company:**

SELF PAY

### VEHICLE

2017 AUDI A4 Prestige Quattro Automatic AWD TFSI 4D SED 4-2.0L Turbocharged Gasoline Gasoline Direct Injection WHITE

VIN: WAUFAF44HN037320	Interior Color:	Mileage In:	Vehicle Out:
License: 729AMV	Exterior Color: WHITE	Mileage Out:	
State: LA	Production Date: 9/2016	Condition: Good	Job #:

**TRANSMISSION**

Automatic Transmission  
4 Wheel Drive

Air Conditioning

Intermittent Wipers  
Tilt Wheel

**RADIO**

CD Player  
Auxiliary Audio Connection

**SEATS**

Bucket Seats  
Leather Seats

**POWER**

Power Steering  
Power Brakes  
Power Windows

Cruise Control

Rear Defogger  
Message Center  
Steering Wheel Touch Controls

**SAFETY**

Drivers Side Air Bag  
Passenger Air Bag  
Anti-Lock Brakes (4)

**WHEELS**

Aluminum/Alloy Wheels

**DECOR**

Tinted Glass  
Console/Storage  
Overhead Console

Telescopic Wheel

Climate Control  
Navigation System  
Parking Sensors

4 Wheel Disc Brakes

Front Side Impact Air Bags  
Head/Curtain Air Bags

**PAINT**

Three Stage Paint  
Traction Control

**CONVENIENCE**

Home Link

Stability Control

Signal Integrated Mirrors

# Preliminary Estimate

---

**RO Number: 13493**

2017 AUDI A4 Prestige Quattro Automatic AWD TFSI 4D SED 4-2.0L Turbocharged Gasoline Gasoline Direct Injection WHITE

Line	Oper	Description	Part Number	Qty	Extended Price \$	Labor	Paint
1	<b>FRONT BUMPER &amp; GRILLE</b>						
2		O/H bumper assy			3.1		
3	*	Rpr Bumper cover w/park sensors			<u>6.0</u>		3.0
4		Add for Three Stage					2.1
5		Repl Add for park sensor		1	m	0.4 M	
6		Repl Aim distance sensor		1	m	1.0 M	
7	#	Repl Flex additive		1	6.00		
8	#	Subl Hazardous waste removal		1	5.00		
9	<b>VEHICLE DIAGNOSTICS</b>						
10	*	Repl Post-repair scan		1	m	<u>1.0</u> M	
			<b>SUBTOTALS</b>		<b>11.00</b>	<b>11.5</b>	<b>5.1</b>

## **ESTIMATE TOTALS**

Category	Basis	Rate	Cost \$
Parts			11.00
Body Labor	9.1 hrs @	\$ 55.00 /hr	500.50
Paint Labor	5.1 hrs @	\$ 55.00 /hr	280.50
Mechanical Labor	2.4 hrs @	\$ 100.00 /hr	240.00
Paint	5.1 hrs @	\$ 42.00 /hr	214.20
<b>Subtotal</b>			<b>1,246.20</b>
Sales Tax	\$ 1,246.20 @	4.4500 %	55.46
Municipal Tax	\$ 1,246.20 @	4.5000 %	56.08
<b>Grand Total</b>			<b>1,357.74</b>

ANY PERSON WHO KNOWINGLY PRESENTS A FALSE OR FRAUDULENT CLAIM FOR PAYMENT OF A LOSS OR BENEFIT OR KNOWINGLY PRESENTS FALSE INFORMATION IN AN APPLICATION FOR INSURANCE IS GUILTY OF A CRIME AND MAY BE SUBJECT TO FINES AND CONFINEMENT IN PRISON.

### RO Number: 13493

2017 AUDI A4 Prestige Quattro Automatic AWD TFSI 4D SED 4-2.0L Turbocharged Gasoline Gasoline Direct Injection WHITE

Estimate based on MOTOR CRASH ESTIMATING GUIDE and potentially other third party sources of data. Unless otherwise noted, (a) all items are derived from the Guide ERA1321, CCC Data Date 10/01/2020, and potentially other third party sources of data; and (b) the parts presented are OEM-parts. OEM parts are manufactured by or for the vehicle's Original Equipment Manufacturer (OEM) according to OEM's specifications for U.S. distribution. OEM parts are available at OE/Vehicle dealerships or the specified supplier. OPT OEM (Optional OEM) or ALT OEM (Alternative OEM) parts are OEM parts that may be provided by or through alternate sources other than the OEM vehicle dealerships with discounted pricing. Asterisk (\*) or Double Asterisk (\*\*) indicates that the parts and/or labor data provided by third party sources of data may have been modified or may have come from an alternate data source. Tilde sign (~) items indicate MOTOR Not-Included Labor operations. The symbol (<>) indicates the refinish operation WILL NOT be performed as a separate procedure from the other panels in the estimate. Non-Original Equipment Manufacturer aftermarket parts are described as Non OEM, A/M or NAGS. Used parts are described as LKQ, RCY, or USED. Reconditioned parts are described as Recond. Recored parts are described as Recore. NAGS Part Numbers and Benchmark Prices are provided by National Auto Glass Specifications. Labor operation times listed on the line with the NAGS information are MOTOR suggested labor operation times. NAGS labor operation times are not included. Pound sign (#) items indicate manual entries.

Some 2021 vehicles contain minor changes from the previous year. For those vehicles, prior to receiving updated data from the vehicle manufacturer, labor and parts data from the previous year may be used. The CCC ONE estimator has a list of applicable vehicles. Parts numbers and prices should be confirmed with the local dealership.

The following is a list of additional abbreviations or symbols that may be used to describe work to be done or parts to be repaired or replaced:

#### SYMBOLS FOLLOWING PART PRICE:

m=MOTOR Mechanical component. s=MOTOR Structural component. T=Miscellaneous Taxed charge category.

X=Miscellaneous Non-Taxed charge category.

#### SYMBOLS FOLLOWING LABOR:

D=Diagnostic labor category. E=Electrical labor category. F=Frame labor category. G=Glass labor category.

M=Mechanical labor category. S=Structural labor category. (numbers) 1 through 4=User Defined Labor Categories.

#### OTHER SYMBOLS AND ABBREVIATIONS:

Adj.=Adjacent. Align.=Align. ALU=Aluminum. A/M=Aftermarket part. Blnd=Blend. BOR=Boron steel.

CAPA=Certified Automotive Parts Association. D&R=Disconnect and Reconnect. HSS=High Strength Steel.

HYD=Hydroformed Steel. Incl.=Included. LKQ=Like Kind and Quality. LT=Left. MAG=Magnesium. Non-Adj.=Non Adjacent. NSF=NSF International Certified Part. O/H=Overhaul. Qty=Quantity. Refn=Refinish. Repl=Replace.

R&I=Remove and Install. R&R=Remove and Replace. Rpr=Repair. RT=Right. SAS=Sandwiched Steel.

Sect=Section. Subl=Sublet. UHS=Ultra High Strength Steel. N=Note(s) associated with the estimate line.

CCC ONE Estimating - A product of CCC Information Services Inc.

The following is a list of abbreviations that may be used in CCC ONE Estimating that are not part of the MOTOR CRASH ESTIMATING GUIDE:

BAR=Bureau of Automotive Repair. EPA=Environmental Protection Agency. NHTSA= National Highway Transportation and Safety Administration. PDR=Paintless Dent Repair. VIN=Vehicle Identification Number.

## Preliminary Estimate

### RO Number: 13493

2017 AUDI A4 Prestige Quattro Automatic AWD TFSI 4D SED 4-2.0L Turbocharged Gasoline Gasoline Direct Injection WHITE

### RECALL INFO

2017 AUDI A4 Prestige Quattro Automatic AWD TFSI 4D SED 4-2.0L Turbocharged Gasoline Gasoline Direct Injection WHITE

VIN: WAUFNAF44HN037320	Interior Color:	Mileage In:	Vehicle Out:
License: 729AMV	Exterior Color: WHITE	Mileage Out:	
State: LA	Production Date: 9/2016	Condition: Good	Job #:

The National Highway Transportation and Safety Administration (NHTSA) has issued 5 safety-related recall notice(s) that may apply to the selected vehicle.

**NHTSA ID: 19V547000      Issued: Jul 7, 19      Number of Vehicles: 00145337**

AIR BAGS:SENSOR:OCCUPANT CLASSIFICATION Volkswagen Group of America, Inc. (Audi) is recalling certain 2018-2019 Audi RS5 Sportback, 2018 S5 Cabriolet, S5 Sportback, S5 Coupe, S4 Sedan, A5 Cabriolet, A5 Sportback, A5 Coupe, and 2017-2018 A4 Sedan and A4 Allroad vehicles. Oxidation on the Passenger Occupant Detection System (PODS) connecting cable may cause the software to misdiagnose a malfunction and disable the passenger air bag. A disabled passenger air bag increases the risk of injury in the event of a crash. Audi will notify owners, and dealers will install cable ties to the harness, free of charge. The recall began September 9, 2019. Owners may contact Volkswagen customer service at 1-800-893-5298. Audi's number for this recall is 74D9.

**NHTSA ID: 18V836000      Issued: Nov 11, 18      Number of Vehicles: 00000012**

AIR BAGS:FRONTAL:PASSENGER SIDE:INFLATOR MODULE Volkswagen Group of America, Inc. (Volkswagen) is recalling certain 2018 Audi A5 Sportback and 2017-2018 Audi A4 Allroad vehicles. A passenger air bag module mounting screw may not have been sufficiently tightened, possibly affecting the deployment of the air bag in the event of a crash. If the air bag does not deploy correctly in the event of a crash, it can increase the risk of an injury. Volkswagen will notify owners, and dealers will inspect the air bag mounting screw, tightening or replacing it as necessary, free of charge. The recall began December 19, 2018. Owners may contact Audi customer service at 1-800-253-2834. Volkswagen's number for this recall is 69Y4.

**NHTSA ID: 17V675000      Issued: Oct 10, 17      Number of Vehicles: 00031323**

STRUCTURE:BODY:DOOR:HINGE AND ATTACHMENTS Volkswagen Group of America, Inc. (Volkswagen) is recalling certain 2017-2018 Audi A4 Sedan and A4 allroad, and 2018 A5 Sportback vehicles. The aluminum trim on the front and rear doors can come loose from around the door speakers, leaving sharp edges exposed. The sharp edges of the speaker trim increase the risk of injury to vehicle occupants. Audi will notify owners, and dealers will replace the speaker cover aluminum trim, free of charge. The recall began March 13, 2018. Owners may contact Audi customer service at 1-800-253-2834. Volkswagen's number for this recall is 70G6.

**NHTSA ID: 16V955000      Issued: Dec 12, 16      Number of Vehicles: 00005947**

AIR BAGS:SIDE/WINDOW Volkswagen Group of America, Inc. (Volkswagen) is recalling certain model year 2017 Audi A7, A4, A6, Volkswagen Golf and Tiguan vehicles and 2016 Volkswagen e-Golf vehicles for driver frontal air bags, passenger frontal air bags or head air bags that may not deploy properly. Additionally, certain 2017 Audi Q7, A4 Sedan, A4 Allroad, and 2018 Audi Q5 vehicles are being recalled because the seat belt pretensioners may not activate properly. In the event of a crash, if the air bags and/or the seat belt pretensioners do not inflate or function properly, the vehicle occupants have an increased risk of injury. Volkswagen and Audi will notify owners, and dealers will replace the affected air bags and seat belt pretensioners, free of charge. The recall began April 2017. Owners may contact Volkswagen customer service at 1-800-893-5298 or Audi customer service at 1-800-253-2834.

**NHTSA ID: 16V642000      Issued: Sep 9, 16      Number of Vehicles: 00079895**

ELECTRICAL SYSTEM: SOFTWARE Volkswagen Group of America, Inc. (Volkswagen) is recalling certain model year 2016 TT roadster, A3 cabriolet, A3 sedan and A3 e-tron, 2016-2017 TT coupe, 2017 A4 sedan and Q7 and 2015-2017 Q3 vehicles. The affected vehicles may have been programmed with new software that inadvertently makes the side marker lights inoperative in conjunction with the parking lights or the headlights. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) number 108, "Lamps, Reflective

## Preliminary Estimate

---

### RO Number: 13493

2017 AUDI A4 Prestige Quattro Automatic AWD TFSI 4D SED 4-2.0L Turbocharged Gasoline Gasoline Direct Injection WHITE

Devices, and Associated Equipment." If the side marker lights do not illuminate, the vehicle may be less visible at night, increasing the risk of a crash. Audi will notify owners, and dealers will upload revised software to correct the issue, free of charge. This recall began November 2016. Owners may contact Audi customer service at 1-800-253-2834. Volkswagen's number for this recall is 97CB.