THE OHIO STATE UNIVERSITY

LOCKOUT TAGOUT PROCEDURE

DESCIRPTION:	
Department/Division Center For Automotive Research Student Projects	Building/Address 930 Kinnear Rd Storage
Equipment ID: N/A	Equipment/system description: Bevel Compound Miter Saw
Location: Student Projects Machine shop	Procedure last updated: 6/03/2025

PURPOSE:
This procedure establishes the minimum requirements necessary to protect employees from injury caused by the unexpected energization, start up, or release of stored energy during service or maintenance. Use this procedure to make sure the machine or equipment is stopped, isolated from all potentially hazardous energy sources, and locked out before any employee begins work.

AUTHORIZATION:
List any authorized persons authorized to lock and tag out the machine or equipment using this procedure:

Sr. Instructional Lab Supervisor
Student Research Assistants

SCOPE:
Provide a description of the scope of work for this service or maintenance work:

To maintain and repair equipment

NOTIFY:
Notify all affected employees that the machine or equipment is to be shut down and locked out for service or maintenance.

Name/Job Title	Notification method
Sr. Instructional Lab Supervisor / Max Wright	Teams message/ Text Message

NORMAL SHUTDOWN:
Shut down the machine or equipment by normal stopping procedures (such as depressing a stop button, opening switches, or closing valves). List types and locations of machine or equipment operating controls.

Shutdown method	Location
Release the trigger to stop the blade rotation.	Top of machine

ISOLATE AND LOCKOUT:
Isolate energy sources using appropriate isolating devices. Lock and tag out the energy isolating devices with assigned individual locks and tags.

THE OHIO STATE UNIVERSITY

WARNING: The following are the known lockout steps. If additional steps are discovered, inform your supervisor, lock them out, and modify this procedure accordingly.

1		**Energy source and magnitude:** **Electrical** **120 Volt** **Energy Isolating Device Location:** **LoTo on wall by exit door** **Isolation device/procedure:** **Unplug from cord from wall and install Lock on plug** **Control Method: lock/tag information *(initial and date)*** Rotating Electrical Plug Lockout **Method to relieve residual/stored energy:** **N/A** **Verification Method** ***Depress trigger to verify zero energy*** **Restored by: (*initial and date*)** Provide initial and date of person removing lock and tag.

Will more than one person will be involved in this procedure?

If you select NO, group LOTO will not be used, skip to next section
If you select YES, a group LOTO will be used, and describe your group LOTO method below

Choose a group LOTO method:	Yes ☐	No ☒
☐ A hasp will be used for this procedure		
☐ A lock box will be used for this procedure Lock box identification #:		
☐ A Primary Authorized Person		
	Name:	

THE MACHINE OR EQUIPMENT IS NOW LOCKED OUT AND SERVICE OR MAINTENANCE CAN BE DONE

RESTORE:
Restore the machine or equipment to service after the service or maintenance is completed

Step 1: Check the machine or equipment and the immediate area around it to make sure all nonessential items have been removed and that the machine or equipment is in operating condition and ready to energize.

Step 2: Make sure all employees are safely positioned for starting or energizing the machine or equipment.

Step 3: Verify that the controls are in neutral.

Step 4: Remove the lockout devices and reenergize the machine or equipment.

Note: Some forms of blocking may require re-energization of the machine before they can be safely removed.

Step 5: Notify affected employees that the servicing or maintenance is completed and the machine or equipment is ready to use.



THE OHIO STATE UNIVERSITY