



How to read this walkthrough

Screens 1–8 follow the integration workflow diagram: install & connect → map cameras → AI candidate queue → Competent Person review → Observation created → work in Procore → verify on camera → audit log. Screen 9 adds a planned Site Risk Heat Map built from human-approved detections. All data is illustrative; nothing has been built against or connected to the Procore API. Procore screens are generic mocks, not Procore's UI.

Screen 1 of 9 · Install from the Procore App Marketplace & choose projects

PROTOTYPE — planned design, not yet deployed




A Procore Company Admin installs wsafe.ai, approves least-privilege permissions for its Developer Managed Service Account (DMSA), and picks which projects the app can access.

Procore API in this step: READ Projects / Company

Screen 2 of 9 · Map existing cameras to Procore projects & locations

PROTOTYPE — planned design, not yet deployed




wsafe.ai reads the project's Locations, Directory, and Observation Types / Hazards / Trades so each existing camera view maps to a Procore project and location, with default trade and assignee.

Procore API in this step: READ Locations READ Directory READ Obs. Types · Hazards · Trades

Screen 3 of 9 · Hazard alert queue — AI candidates awaiting human review

PROTOTYPE — planned design, not yet deployed




Models flag candidate hazards with a snapshot, a hazard type, and a suggested OSHA reference. Candidates, video, and rejected items stay inside wsafe.ai.

Procore API in this step: — No Procore call

Screen 4 of 9 · Competent Person review — approve, edit, or reject

PROTOTYPE — planned design, not yet deployed




A person confirms the hazard, OSHA reference, trade, location, priority, and assignee using the customer's own Procore lists. Nothing is written to Procore until they approve.

Procore API in this step: — No Procore call until Approve

Screen 5 of 9 · Approved → Safety Observation created in Procore

PROTOTYPE — planned design, not yet deployed




On approval, wsafe.ai uploads the snapshot to Photos and creates a Safety Observation with every field prefilled. Procore notifies the assignee. A Near Miss incident is optional and reviewer-initiated.

Procore API in this step: CREATE Photos (Uploads) CREATE Observations CREATE Incidents · optional

Screen 6 of 9 · The Observation in Procore (generic mock)

PROTOTYPE — planned design, not yet deployed




The field team works the item in Procore's own Observations workflow — no new app for the foreman. Generic mock for illustration only; not the actual Procore UI.

Procore API in this step: READ Webhook · Observations update

Screen 7 of 9 · Verify on camera & close the loop

PROTOTYPE — planned design, not yet deployed




A Procore webhook reports the status change. wsafe.ai re-checks the camera view, and the reviewer posts the 'after' photo back to the Observation as a Response Log.

Procore API in this step: READ Observation + Response Logs · CREATE Photos · UPDATE Observations (Response Log)

Screen 8 of 9 · Audit log — detect → review → assign → correct → verify

PROTOTYPE — planned design, not yet deployed




Every AI flag, human decision, and Procore API call is recorded with actor and time. wsafe.ai never deletes Procore records.

Procore API in this step: — No DELETE — ever

Screen 9 of 9 · Site Risk Heat Map — where approved hazards concentrate

PROTOTYPE — planned design, not yet deployed



Human-approved detections roll up by Procore Location, weighted by recency, OSHA severity, and camera coverage hours. It ranks zones for inspections and toolbox talks; it does not predict incidents.

Procore API in this step: READ Locations · Observations · READ Incidents · Phase 2 · CREATE Observation · on approval · CREATE Photo / Inspection · Phase 2

Method (planned design): the relative likelihood score uses human-approved detections only, weighted by recency, severity (OSHA category), and exposure (camera coverage hours). Near Miss / Incident data read from Procore can inform the weights. No predictive accuracy is claimed. Pushing the map image or creating an Inspection is Phase 2.