

DAMAGE PHOTO DOCUMENTATION

Claim Number: GD-2024-30545

Claimant: Ingrid Huber

Date of Photos: 2024-03-04

Damage Type: Glass Damage

Damaged Object: conservatory glass roof panel

Location: 45127 Essen

PHOTO EVIDENCE:

Photo 1: Full view of the shattered conservatory glass roof panel. Spider-web crack pattern visible across the entire pane.

Photo 2: Close-up of the point of impact on the conservatory glass roof panel. Clear radial fracture lines emanating from center.

Photo 3: Glass fragments on the floor below the conservatory glass roof panel. Safety concern documented.

Photo 4: The frame and mounting of the conservatory glass roof panel showing condition for replacement assessment.

Photo 5: Temporary boarding/covering installed over the damaged conservatory glass roof panel for security.

DAMAGE ASSESSMENT NOTES:

The photographs above document the damage to the conservatory glass roof panel at the property of Ingrid Huber in Essen.

A falling object from the floor above hit the conservatory glass roof panel, shattering it completely. The conservatory glass roof panel pieces have been safely removed. Urgent replacement is required for weather protection.

The damage was first discovered on 2024-03-03.

These photographs were taken on 2024-03-04 to document the current condition for insurance claim processing.

Assessment: The conservatory glass roof panel requires complete replacement.

Documented by: Ingrid Huber