

DAMAGE PHOTO DOCUMENTATION

Claim Number: GD-2024-19248

Claimant: Markus Leitner

Date of Photos: 2025-04-09

Damage Type: Glass Damage

Damaged Object: conservatory glass roof panel

Location: 55116 Mainz

PHOTO EVIDENCE:

Photo 1: Full view of the shattered conservatory glass roof panel. Spider-web crack pattern visible across the entire pane.

Photo 2: Close-up of the point of impact on the conservatory glass roof panel. Clear radial fracture lines emanating from center.

Photo 3: Glass fragments on the floor below the conservatory glass roof panel. Safety concern documented.

Photo 4: The frame and mounting of the conservatory glass roof panel showing condition for replacement assessment.

Photo 5: Temporary boarding/covering installed over the damaged conservatory glass roof panel for security.

DAMAGE ASSESSMENT NOTES:

The photographs above document the damage to the conservatory glass roof panel at the property of Markus Leitner in Mainz.

During a break-in attempt, the intruder smashed the conservatory glass roof panel. While nothing was stolen, the conservatory glass roof panel is completely destroyed. Police report has been filed (reference included).

The damage was first discovered on 2025-04-08.

These photographs were taken on 2025-04-09 to document the current condition for insurance claim processing.

Assessment: The conservatory glass roof panel requires complete replacement.

Documented by: Markus Leitner