

DAMAGE PHOTO DOCUMENTATION

Claim Number: GD-2024-64105

Claimant: Klaus Weber

Date of Photos: 2024-04-05

Damage Type: Glass Damage

Damaged Object: skylight window

Location: 20095 Hamburg

PHOTO EVIDENCE:

Photo 1: Full view of the shattered skylight window. Spider-web crack pattern visible across the entire pane.

Photo 2: Close-up of the point of impact on the skylight window. Clear radial fracture lines emanating from center.

Photo 3: Glass fragments on the floor below the skylight window. Safety concern documented.

Photo 4: The frame and mounting of the skylight window showing condition for replacement assessment.

Photo 5: Temporary boarding/covering installed over the damaged skylight window for security.

DAMAGE ASSESSMENT NOTES:

The photographs above document the damage to the skylight window at the property of Klaus Weber in Hamburg.

The skylight window shattered unexpectedly due to thermal stress. Glass fragments were found across the room. Temporary boarding has been applied for security. Professional glazier assessment confirms the skylight window needs full replacement.

The damage was first discovered on 2024-04-04.

These photographs were taken on 2024-04-05 to document the current condition for insurance claim processing.

Assessment: The skylight window requires complete replacement.

Documented by: Klaus Weber