
Highest service efficiency under a fan-delivery stress test
q=1: nominal fan profile
q=0: no added air speed at occupied positions
Fan air-speed delivery fraction q
1.0
0.8
0.6
0.4
0.2
0.0
20
30
40
50
60
70
80
Ambient relative humidity (%)
C: no winning cells
B: evaporative
A: fan