

Careful with output comb
for analog systems
 $\Rightarrow$ glitches

