Highlights

- Joint steering, feedrate and preview decisions generate CNC command trajectories.
- Planar kinematic projection enforces velocity, acceleration and jerk limits.
- Startup and braking are refined with complete-trajectory feasibility checks.