HW probe of HP 1998 Desktop Computer (EliteDesk 800 G1 SFF) #4af6b915c2

linux-hardware.org

Discuss this probe on our forum.

BUS	ID / Class	Vendor	Device	Type	Driver	Status
PCI	10de:1d01:19da:2476 » / 03-00-00	NVIDIA Corporation	GP108 [GeForce GT 1030]	graphics card	nvidia	works ⓘ
PCI	10de:0fb8:19da:2476 » / 04-03-00	NVIDIA Corporation	GP108 High Definition Audio Controller	sound	snd_hda_intel	detected
PCI	8086:8c20:103c:1998 » / 04-03-00	Intel Corporation	8 Series/C220 Series Chipset High Definition Audio Controller	sound	snd_hda_intel	detected
PCI	8086:153a:103c:1998 » / 02-00-00	Intel Corporation	Ethernet Connection I217-LM	network	e1000e	detected ⓘ
PCI	8086:2725:8086:0020 » / 02-80-00	Intel Corporation	Wi-Fi 6 AX210/AX211/AX411 160MHz	network	iwlwifi	works 💬
PCI	8086:8c02:103c:1998 » / 01-06-01	Intel Corporation	8 Series/C220 Series Chipset Family 6-port SATA Controller 1 [AHCI mode]	storage	ahci	works
PCI	8086:0c00:103c:1998 » / 06-00-00	Intel Corporation	4th Gen Core Processor DRAM Controller	bridge	hsw_uncore	detected
PCI	8086:0c01:103c:1998 » / 06-04-00	Intel Corporation	Xeon E3-1200 v3/4th Gen Core Processor PCI Express x16 Controller	bridge	pcieport	works
PCI	8086:8c10:103c:1998 » / 06-04-00	Intel Corporation	8 Series/C220 Series Chipset Family PCI Express Root Port #1	bridge	pcieport	detected
PCI	8086:8c12:103c:1998 » / 06-04-00	Intel Corporation	8 Series/C220 Series Chipset Family PCI Express Root Port #2	bridge	pcieport	works
PCI	8086:8c4e:103c:1998 » / 06-01-00	Intel Corporation	Q87 Express LPC Controller	bridge	lpc_ich	detected
PCI	8086:8c3a:103c:1998 » / 07-80-00	Intel Corporation	8 Series/C220 Series Chipset Family MEI Controller #1	communication controller	mei_me	detected ⓘ

PCI	8086:8c3d:103c:1998 » / 07-00-02	Intel Corporation	8 Series/C220 Series Chipset Family KT Controller	serial controller (16550)	serial	detected
PCI	8086:8c22:103c:1998 » / 0c-05-00	Intel Corporation	8 Series/C220 Series Chipset Family SMBus Controller	smbus	i801_smbus	detected
PCI	8086:8c26:103c:1998 » / 0c-03-20	Intel Corporation	8 Series/C220 Series Chipset Family USB EHCI #1	usb controller	ehci_hcd	detected
PCI	8086:8c2d:103c:1998 » / 0c-03-20	Intel Corporation	8 Series/C220 Series Chipset Family USB EHCI #2	usb controller	ehci_hcd	detected
PCI	8086:8c31:103c:1998 » / 0c-03-30	Intel Corporation	8 Series/C220 Series Chipset Family USB xHCI	usb controller	xhci_hcd	detected
USB	0bda:8771 » / e0-01-01	Realtek Semiconductor Corp.	Bluetooth Radio	bluetooth	btusb	detected ⓘ
USB	1d6b:0002 » / 09-00-00	Linux Foundation	2.0 root hub	hub	hub	detected
USB	1d6b:0003 » / 09-00-00	Linux Foundation	3.0 root hub	hub	hub	detected
USB	8087:8000 » / 09-00-00	Intel Corp.	Integrated Rate Matching Hub	hub	hub	detected
USB	8087:8008 » / 09-00-00	Intel Corp.	Integrated Rate Matching Hub	hub	hub	detected
USB	00da:8510 » / 03-01-02	Telink	Wireless Receiver	mouse	usbhid	detected
EISA	philips-phlc21a »	Philips	PHL 272V8 PHLC21A 1920x1080 598x336mm 27.0-inch	monitor	-	works
SYS	hewlett-packard-l01-v02-59-03-16-2015 »	Hewlett-Packard	BIOS L01 v02.59 03/16/2015	bios	-	works
SYS	intel-6-60-3-core-i7-4770 »	Intel	Core i7-4770 CPU @ 3.40GHz	cpu	-	works
SYS	corsair-cmv8gx3m1a1600c11-dimm [AAE] »	Corsair	RAM CMV8GX3M1A1600C11 8GB DIMM DDR3 1600MT/s	memory	-	works
SYS	corsair-cmv8gx3m1a1600c11-dimm [AAE] »	Corsair	RAM CMV8GX3M1A1600C11 8GB DIMM DDR3 1600MT/s	memory	-	works
SYS	crucial-ct102464bd160b-m16-dimm [8B1] »	Crucial	RAM CT102464BD160B.M16 8GB DIMM DDR3 1600MT/s	memory	-	works
SYS	samsung-m378b5173db0-ck0-dimm [67F] »	Samsung	RAM M378B5173DB0-CK0 4GB DIMM DDR3 1600MT/s	memory	-	works
SYS	hewlett-packard-1998 »	Hewlett-Packard	Motherboard 1998	motherboard	-	works
SCSI	hl-dt-st-dvd-rw-gt50n »	HL-DT-ST	DVD+-RW GT50N	cdrom	ahci, sr	detected
SERIAL	serial-console »		serial console	keyboard	-	detected 💬

| IDE | samsung-ssd-870-evo-500gb [F7B] » | Samsung | SSD 870 EVO 500GB | disk | ahci, sd | works ⓘ |

ⓘ Export template to forum (BBCode)

ⓘ Find compatible parts for upgrade

ⓘ How it fits BSD?