```
76543210
                        E - error; D - done;
     E|D|B|T|
                        B - busy; T - trigger;
                        0 \times 40 = 010000000
  char status;
  status = 0 \times 40;
                       /* set 'D' bit */
if (status & 0x40); /* test 'D' bit */
status &= \sim 0 \times 40; /* clear 'D' bit */
```