```
76543210
                       E - error; D - done;
                       B - busy; T - trigger;
                       0 \times 40 = 010000000
  */
  char status;
 status |= 0x40;
                      /* set 'D' bit */
10 if (status & 0x40); /* test 'D' bit */
status &= ~0x40; /* clear 'D' bit */
```