
## builddriver.sh

```
1.
 2.
      # marvell build tools dir
3.
      gcc_dir=/home/walterzh/work/2016-05-LSP/gerrit/build-bundle/poky/build/tmp/s
      ysroots/x86 64-linux/usr/bin/arm-poky-linux-gnueabi
4.
      PATH=$PATH:${gcc_dir}
 5.
6.
      export WORKDIR=/home/walterzh/work/2016-05-LSP/gerrit/build-bundle/poky/buil
      d/tmp/work/granite2-poky-linux-gnueabi
      KERNEL_REV=3.18.7+gitAUTOINC+7019c4a279-r0
      export STAGING_KERNEL_DIR=${WORKDIR}/linux-granite-upstream/${KERNEL_REV}/li
8.
      nux-granite2-standard-build
9.
10.
11.
      export KERNELDIR=${STAGING KERNEL DIR}
      export CROSS_COMPILE=arm-poky-linux-gnueabi-
12.
13.
      export ARCH=arm
14.
15.
      #make ARCH=arm CROSS_COMPILE=arm-poky-linux-gnueabi- -C ${STAGING_KERNEL_DIR
      make ARCH=arm CROSS_COMPILE=arm-poky-linux-gnueabi-
16.
```

kgtp depends on CONFIG\_PERF\_EVENT and CONFIG\_KPROBES 在make menuconfig中配置如下

## 进入Generic Setup



选择enable KProbes



选择enable Performance Event



kgtp (20130706 edition)在kernel 3.18.7下build,出错如下

```
walterzh@walterzh-Precision-T1650:~/work/current/kgtp$ bash builddrivers.sh
1.
      make ARCH=arm CROSS_COMPILE=arm-poky-linux-gnueabi- -C /home/walterzh/work/2
      016-05-LSP/gerrit/build-bundle/poky/build/tmp/work/granite2-poky-linux-gnuea
      bi/linux-granite-upstream/3.18.7+gitAUTOINC+7019c4a279-r0/linux-granite2-sta
      ndard-build M=/home/walterzh/work/2016-05-LSP/kgtp modules
 3.
      make[1]: Entering directory `/home/walterzh/work/2016-05-LSP/gerrit/build-bu
      ndle/poky/build/tmp/work/granite2-poky-linux-gnueabi/linux-granite-upstream/
      3.18.7+gitAUTOINC+7019c4a279-r0/linux-granite2-standard-build'
4.
        CC [M] /home/walterzh/work/2016-05-LSP/kgtp/gtp.o
5.
      /home/walterzh/work/2016-05-LSP/kgtp/gtp.c: In function 'gtp_handler_enable_
      disable':
      /home/walterzh/work/2016-05-LSP/kgtp/gtp.c:4162:4: error: implicit declarati
6.
      on of function 'add_preempt_count' [-Werror=implicit-function-declaration]
          add_preempt_count(HARDIRQ_OFFSET);
7.
8.
9.
      /home/walterzh/work/2016-05-LSP/kgtp/gtp.c:4167:4: error: implicit declarati
      on of function 'sub_preempt_count' [-Werror=implicit-function-declaration]
10.
          sub_preempt_count(HARDIRQ_OFFSET);
11.
12.
      cc1: some warnings being treated as errors
13.
      make[4]: *** [/home/walterzh/work/2016-05-LSP/kgtp/gtp.o] Error 1
      make[3]: *** [_module_/home/walterzh/work/2016-05-LSP/kgtp] Error 2
14.
      make[2]: *** [sub-make] Error 2
15.
      make[1]: *** [__sub-make] Error 2
16.
      make[1]: Leaving directory `/home/walterzh/work/2016-05-LSP/gerrit/build-bun
17.
      dle/poky/build/tmp/work/granite2-poky-linux-gnueabi/linux-granite-upstream/3
      .18.7+gitAUTOINC+7019c4a279-r0/linux-granite2-standard-build'
      make: *** [gtp.ko] Error 2
18.
```

是不是高版本的kernel已经remove add\_preempt\_count() / sub\_preempt\_count()了呢?