

Hdmi Q&A



Q1: SSD268G and ddr3 find that the operation is unstable, it cannot be started or runs abnormally for a period of time?

The analysis ideas are as follows: 1. Confirm whether it is completely in accordance with our PCB and laminate design. 2. Confirm whether the IPL is used correctly (whether it is the IPL corresponding to the PCB). 3. Confirm whether the posted DDR particles are 1866 or 2133.