

4321 Blast Off Way Electric City, TX 98765 Ph: 800-fix-tesla

Email: fixtesla@tesla.com

Estimate... # 1023 Gwynne, Shotwell

Model 3

Last	Shotwell	Model	Model	3 Insurance	
First	Gwynne	VIN	4656AAA2WE6546611	# Claim	122WQ
Cell	310-896-5421	License	AS12312C	Policy	QWQW12
Other	310-445+7412	Color	RED	Adjuster	adjuster
Email	gwynne@spacex.com	Year	2018	Phone	9898989898
CNOTES	test	Style	XUV	Email	adjuster@allstate.com

			\$	Labor	Paint
1	RT REAR DOOR PANEL	1081458S0F	705.00	4.90	2.80
2	Upper bracket bolt	103168300B	0.55	0.00	0.00
3 R&I	RT FRONT DOOR PANEL	1081438S0G	0.00	5.00	0.00
4	RT Upper bracket	108418200B	6.60	0.20	0.00
5	RT Upper bracket	108418200B	6.60	0.20	0.00
6	RT Upper bracket	108418200B	6.60	0.20	0.00
7	RT Upper bracket	108418200B	6.60	0.20	0.00
8	RT Upper bracket	108418200B	6.60	0.20	0.00
9	RT Upper bracket	108418200B	6.60	0.20	0.00
10	RT Upper bracket	108418200B	6.60	0.20	0.00
11	RT Upper bracket	108418200B	6.60	0.20	0.00
12	RT Upper bracket	108418200B	6.60	0.20	0.00
13	RT Upper bracket	108418200B	6.60	0.20	0.00
14	RT Upper bracket	108418200B	6.60	0.20	0.00
15	LT Upper bracket	108418100B	6.60	0.20	0.00
16	Upper bracket bolt	103168300B	0.55	0.00	0.00
17BLN	Bumper cover unpainted	1084168S0E	0.00	0.00	2.80
18	HOOD	1081390E0B	495.00	1.20	2.70
19	RT Side bracket	110454100B	6.60	0.20	0.00
20	RT Inner bracket	108417200E	8.80	0.20	0.00
21	LT Upper bracket	108418100B	6.60	0.20	0.00
22	LT Upper bracket	108418100B	6.60	0.20	0.00
23	LT Upper bracket	108418100B	6.60	0.20	0.00
24	Upper bracket bolt	103168300B	0.55	0.00	0.00
25	LT Upper bracket	108418100B	6.60	0.20	0.00
26	LT Inner bracket	108417100E	8.80	0.20	0.00
27	Inner bracket screw	112895100B	0.50	0.00	0.00

ESTIMATE. #1023 NAME: Gwynne, Shotwell

28RPR	RT Inner bracket	108417200E	8.80	5.00	0.00
29	LT Side bracket	110454000B	6.60	0.20	0.00
30	Side bracket screw	101280900A	0.50	0.00	0.00
31	Bumper cover unpainted	1084168S0E	495.00	3.50	2.80
32	Bumper cover nut	100653800A	0.55	0.00	0.00
33	RT Side bracket	110454100B	6.60	0.20	0.00
34	RT Inner bracket	108417200E	8.80	0.20	0.00
35	Bumper cover screw	101280900A	0.50	0.00	0.00
36	RT Upper bracket	108418200B	6.60	0.20	0.00
37	Side bracket screw	101280900A	0.50	0.00	0.00
38	Bumper cover screw	101280900A	0.50	0.00	0.00
39	RT Side bracket	110454100B	6.60	0.20	0.00
40	Side bracket screw	101280900A	0.50	0.00	0.00
41	RT Upper bracket	108418200B	6.60	0.20	0.00
42	Upper bracket bolt	103168300B	0.55	0.00	0.00
43	Bumper cover screw	101280900A	0.50	0.00	0.00
44	Side bracket screw	101280900A	0.50	0.00	0.00
45	LT Side bracket	110454000B	6.60	0.20	0.00
46	LT Upper bracket	108418100B	6.60	0.20	0.00
47	Upper bracket bolt	103168300B	0.55	0.00	0.00
480VL	Bumper / Hood	None	None	-0.60	-0.70

LABOR	Units	Rate L	abor \$	Item	\$	To	otals
Paint	11.10@	30.00	333.00	Parts	1895.90		
Body	25.00@	40.00	1000.00	PaintMat	0.00		
Mech	0.00@	0.00	0.00	BodyMat	0.00	Total Items	1895.90
Frame	0.00@	0.00	0.00	HazWaste	0.00	Total Labor	1333.00
Struct	0.00@	0.00	0.00	Sublet	0.00	_	
Glass	0.00@	0.00	0.00	Aft/Mkt	0.00	Subtotal	3228.90
Detail	0.00@	0.00	0.00	Towing	0.00		
Other	0.00@	0.00	0.00	Storage	0.00	Tax	8.25
				Misc #1	0.00	_	
				Misc #2	0.00	Grand Total	3385.31
				Misc #3	0.00		