
a Warm-up
Die temperature (°C)
Minutes since start
Synchronous
Phased
Synchronous, s + s
Phased, s + s
b One point per run
Steady die temperature (°C)
Compute duty, D
c Fan response
Fan speed (min⁻¹)
Steady die temperature (°C)
Independent timers
Serialised cycle
Synchronous
Phased
Synchronous, 2 threads
Phased, 2 threads
Synchronous, s + s
Phased, s + s