



- → Good shim coils nessesary
- → Sensor accuracy/noise?
 - → Longer averaging?





